

21812
(MAINTENANCE)

Schedule XLV-Form No. 134 ✓

344.

THAUSA MAIN ROAD TO BASBUTHA

DIVISION

SUB-DIVISION

RANJEET KUMAR

MEASUREMENT BOOK

1359.

3rd year maintenance

11

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/WORK - const ⁿ of road from Thanga main road to Basbura underpass (S) Agency - Rangest Kune Aft no - 41/SBD/MAY/2020 Date of start :- 24/2/2020 Time of completion - 23/2/21 Date of actual const ⁿ - Date of meas - <u>meas.</u>					
(1)	Restoration of road surface Soil also - do as per $2500 \times 2 \times 1.125 \times 0.3125$ $\times 8.4\% = 177.18 m^3$				
(2)	making up of kerbs shoulder also - do $2500 \times 2 \times 1.125 \times 1.25 \times 12\%$ $= 843.75 m^3$				
(3)	Repair of pot hole with 7mm mesh do - do as per $2200m \times 3.75 \times 1.25 \times 0.075$ $\times 1.5\% = 11.60 m^3$				
(4)	Pot repair over pot holes with				

Continuation

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(10)					
white washing					
of parapet wall					
of compound					
as per					
					84 m ²
(11)					
maintenance of tree					
plantation as per					
as per					
90 NRS @ 2 90 NRS					

