

*(Maintenance)*

# Schedule XLV-Form No. 134

HETH CHAKRAI - PANDEDIH PHUSY ROAD

to GOSHAIDEN

DIVISION

SUB-DIVISION

*RANJEET KUMAR*

MEASUREMENT BOOK

1304

| Particulars                              | Details of actual measurement |    |    |    | Contents of area |
|------------------------------------------|-------------------------------|----|----|----|------------------|
|                                          | No.                           | L. | B. | D. |                  |
| 1/Work:- const <sup>n</sup> of road from |                               |    |    |    |                  |
| He to Chak in Pandeloh                   |                               |    |    |    |                  |
| Pmmy road to Goseidoh                    |                               |    |    |    |                  |
| under mmsy (SC)                          |                               |    |    |    |                  |
| 2/Agency:- Rangit Kumar                  |                               |    |    |    |                  |
| Hgt no - 37/SBD/mmsy/20-21               |                               |    |    |    |                  |
| Date of start:- 14/2/2020                |                               |    |    |    |                  |
| Time of completion:- 13/7/21             |                               |    |    |    |                  |
| Date of measurement                      |                               |    |    |    |                  |
|                                          |                               |    |    |    |                  |
|                                          |                               |    |    |    |                  |
|                                          |                               |    |    |    |                  |
|                                          |                               |    |    |    |                  |
|                                          |                               |    |    |    |                  |

measured

- ① Restoration of  
rain cuts with  
soil do - do as  
per 11

$$1600 \times 2 \times 1.125 \times 0.30 \times 125 \\ \times 8.4\% = 113.4 \text{ m}^3$$

- ② making up of bums  
and shoulder  
as per Purvis

$$1600 \times 2 \times 1.125 \times 1.25 \times 12\% \\ = 540 \text{ m}^3$$

- ③ Repair of pot hole  
fill on do - do

Continuation

Continuation

| Particulars | Details of actual measurement |    |    |                 | Contents of area |
|-------------|-------------------------------|----|----|-----------------|------------------|
|             | No.                           | L. | B. | D.              |                  |
|             |                               |    |    | B + Rs 45720377 |                  |
|             | Less w:                       |    |    | ⊖ Rs 45720377   |                  |
| (ii)        | Bonus                         |    |    | R.S.: 41148377  |                  |
|             | Jn                            |    |    |                 |                  |
|             | 20/7/24                       |    |    |                 |                  |
|             | STE                           |    |    |                 |                  |
| (iii)       |                               |    |    |                 |                  |
|             |                               |    |    | (IN)            |                  |
|             |                               |    |    |                 |                  |
|             |                               |    |    |                 |                  |
|             |                               |    |    |                 |                  |
|             |                               |    |    |                 |                  |
|             |                               |    |    |                 |                  |