

4th years maintenance

65

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: 1062 to					
Narayanpur Primary school					
Dhamelpur sirma					
2. Name of Agency: Rakesh Kumar					
3. Agreement No: 64/9BD/2020-21					
4. Actual/dt. of completion: 17.02.2021					
work done					
① Restoration of green cuts with soil					
1 x 10.50 x 0.90 x 0.30 =					2.835
1 x 20.60 x 0.85 x 0.32 =					5.603
5 x 20.85 x 0.70 x 0.30 =					21.89
6 x 10.60 x 0.72 x 0.30 =					13.937
3 x 30.0 x 0.80 x 0.30 =					36.0
2 x 5.0 x 0.82 x 0.32 =					2.624
1 x 20.60 x 0.84 x 0.32 =					5.537
					Qty = 108.935 m ³
					Safe Qty = 108.14 m ³
② 1/2 maintenance of earthen					
shoulder - elu - 202					
5 x 20.60 x 0.30 =					92.70
8 x 20.90 x 0.85 =					142.12
10 x 30.0 x 0.82 =					246.0
5 x 20.60 x 0.75 =					77.25
2 x 42.68 x 0.50 =					42.68
					Qty = 600.75 m ²
③ 1/2 Repair to pot holes with					
seal surfacing with					
1 x 1.20 continuation =					0.816 m ²
					C.O. Qty = 0.816 m ²

Continuation