

5th years maintenance

76

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work	Lo 28 (machhni to mahesli) Basantpur Gaush.				
2. Name of Agency	Abhay Kumar Thakur				
3. Agreement No.	162 SBD/2018-19				
4. Actual d. of completion	06.02.2020				
Work done					
① Restoration of rain cuts					
1 with soil duplex					
1x	20.50	1.00	0.30		6.15
2x	10.50	1.00	0.30		6.30
4x	20.60	0.90	0.32		23.73
5x	18.90	0.80	0.30		22.68
4x	10.50	0.75	0.32		8.568
3x	8.50	0.72	0.30		5.508
8x	20.50	0.65	0.32		34.112
4x	18.90	0.72	0.30		16.329
6x	10.50	0.68	0.32		13.71
3x	18.10	0.65	0.30		10.588
4x	18.95	0.75	0.30		17.055
1x	10.50	0.75	0.32		2.520
				Qty = 167.25m ³	
				Say Qty 167.12m ³	
② 1/2 Maintenance of earthen					
Shoulder elutri					
1x	20.50	1.0			20.50
1x	10.90	1.0			10.90
1x	20.60	0.90			18.54

Continued

Scanned with CamScanner