

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(3) Repair to pot hole					
Filled 75 mm bitm					
5.386 m ³ bitm P-70					53421
5.386 m ³ @ 8924.48/m ³					48065
(4) Patch repair to pot holes P. 20mm thick Bitum/Carpet					
79.82 m ² bitm P-71					
79.82 m ² @ 245.16/m ²					= 19569
(5) Patch repair to pot holes bitum/Carpet					
P. 20mm Bitum/Carpet					
78.73 m ² bitm P-72					
78.73 m ² @ 259.1/m ²					= 20398
(6) Maint of road					
Sign					
0.26 km @ 14 km P-73					15.24
0.26 km @ 1066.5/km					= 277
Total					161.761
Less 0.25% below rate					324
Total					161437
19.12.2023					
19.12.2023					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- main + of road from Teg Hila Harbans for road to padar.					
Agency:- Binod Kuro					
Agreement:- 8/10/18-19.					
Actual date of sample:- 7.03.22					
(1) Restoration of Rain Cut.					
12 NOX	1.5 m	1.5	0.30		8.1 m ³
15 NOX	1.25 m	1.2	0.30		6.75 m ³
17 NOX	1.45 m	1.25	0.30		9.24 m ³
22 NOX	1.75 m	1.25	0.35		16.84 m ³
12 NOX	4 m	1.25	0.35		21 m ³
10 NOX	7 m	1.25	0.35		30.62 m ³
10 NOX	6.5 m	1.25	0.35		27.62 m ³
					120.17 m ³
(2) making up of berm/shoulder filling Fresh Soil.					
28 NOX	5 m	0.85	2		119 m ³
32 NOX	1.5 m	0.80			384 m ³
12 NOX	7 m	0.85	3		71.4 m ³
21 NOX	9 m	0.85			60.65 m ³
					658.55 m ³
(3) Repair potholes filled with 75 mm mm					
15 NOX	1.7 m	0.50 m	0.75		3.56 m ³
4 NOX	2 m	0.70 m	0.75		4.2 m ³
					13.76 m ³

Continuation