

कार्यपालक अभियंता का कार्यालय

ग्रामीण कार्य विभाग, कार्य प्रमंडल, धमदाहा (पूर्णियाँ)

ईमेल- eerwddhamdaha@gmail.com

पत्रांक- 268

दिनांक- 08/3/25

प्रेषक ,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल धमदाहा।

सेवा में ,

नोडल पदाधिकारी
नई अनुरक्षण नीति 2018
ग्रामीण कार्य विभाग, बिहार , पटना।

विषय :- "नई अनुरक्षण नीति 2018" के अंतर्गत किये गए कार्यों के विरुद्ध आवंटन उपलब्ध कराने के सम्बन्ध में।

महाशय ,

उपर्युक्त विषय के संबंध में कहना है कि इस प्रमंडलाधीन "नई अनुरक्षण नीति 2018" के अंतर्गत किये गए कार्यों के विरुद्ध भुगतान करने हेतु कुल **249.08879 लाख** रुपये मात्र आवंटन की आवश्यकता है। जिसे विहित प्रपत्र में भरकर इस पत्र के साथ संलग्न की जा रही है।

अतः अनुरोध है कि अधियाचित राशि का आवंटन उपलब्ध कराने की कृपा की जाय।

अनु०- (1) अधियाचना का प्रपत्र एवं UC

(2) Bump Indicator Report

विश्वासभाजन

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल धमदाहा।

06/03/25

06/03/25

Utilization Certificate up to March 2025 For Rural Road Maintenance Policy 2018 under office of the Executive Engineer RWD Work Division, Dhamdaha (Purnea)

From,

Name of PIU/Executive Engineer
R.W.D, Work Division, Dhamdaha (Purnea)

To,

NODAL OFFICER
Rural Road Maintenance Policy 2018 , Bihar, Patna

Sl. No.	Name Scheme	Sanction No. & Date with Amount	Amount Received (in Lacs Rs.)	Particular
1	2	3	4	5
1	Construction of Rural roads under Rural Road Maintenance Policy 2018	Secretary cum Empowered Officer, BRRDA Rural Road Maintenance Policy 2018 Total Amounting Rs.1,43,97,65,561	Rs.1,43,97,65,561	Certified that out Rs.1,43,97,65,561 only of grants in aid sanctioned during and up to year 2024-25 in favor of officer-in-charge/PIU/E.E, RWD work Division, Kishanganj-1.A sum Rs 1,43,90,29,084 has been utilize for the purpose of Rural Road Maintenance Policy 2018 Programmed fund as given in the margin for which it was sanctioned and that the balance of Rs. 7,36,477 remaining unutilized as the end of the period under report.

Certified that I have satisfied myself that the condition on which the grants in-aid was sanction have been only fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which in was sanctioned.


Kind of Check Exercised:-

- Works have been supervised by Executive Engineer/Superintend Engineer.
- Periodic Inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction Material have tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer.
- All other codas formalities have been observed.

Physical Progress achieved.

- Construction of road works.
- Construction of CD works.


Sr. Divisional Accounts Officer
R.W.D works division, Dhamdaha


Executive Engineer
R.W.D works division, Dhamdaha


RWD Works Division, Dhamdaha (Dist :- Purnea)

Requisition Format for Scheme Head- MR (3054) Under Bihar Rural Road " New Maintenance Policy 2018" (Initial Rectification and Surface Renewal)

Name of Division:- Dhamdaha

S.N	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (A.A) Letter No. & Date	Administrative Approval (A.A)		Agreement Amount (in Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI in MM/XM (in MM)	Thickness of Bitumen Layer (in MM)	Value of Bitumen Content (in %)	Previous Total Allocated Amount (in Lakh)	Up-to -date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (K.M)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/PU/DHA /24/0005	L070 - T01 to Ful Tola (VR70)	21105302128	Lt No.-1086 , Dt- 01.03.2024	2.315	135.06000	100.67523	20.45255	70/MBD/2024-25 Dt- 28/10/2024	30/04/2025	-	2176	25	5.01	0	0	100.62523	Surface Completed
2	RM/PU/DHA /24/0005	DHAMDAHA KEROSIN TEL DIPIU To CHANDRAHI SATSANG BHAWAN	21105312014	Lt No.-1086 , Dt- 01.03.2024	3.240	198.86800	148.50356	28.57180	70/MBD/2024-25 Dt- 28/10/2024	30/04/2025	-	2294	25	5.02	0	0	148.46356	Surface Completed
Total :-																		249.08879

[Signature]
Sr. Divisional Accounts Officer
RWD Works Division, Dhamdaha

[Signature]
Executive Engineer
RWD Works Division, Dhamdaha

Lab Job number :Rwd Dhamdaha

Date :06-03-2025

Name of Customer :Rohit Raj

Name of Work/ Road :Dhamdaha kerosin tel dipu to chandrahi
satsang bhawan

Sr.no	Location o' Corrected U.I test(in km) value(mm/km)	Road catagory
2	0.1	1950 G
3	0.2	2177 G
4	0.3	2177 G
5	0.4	3086 G
6	0.5	1950 G
7	0.6	2177 G
8	0.7	2177 G
9	0.8	1722 G
10	0.9	1950 G
11	1	3426 G
12	1.1	1722 G
13	1.2	3199 G
14	1.3	3654 G
15	1.4	2177 G
16	1.5	2745 G
17	1.6	1836 G
18	1.7	2290 G
19	1.8	1950 G
20	1.9	1950 G
21	2	2290 G
22	2.1	1722 G
23	2.2	2290 G
24	2.3	2518 G
25	2.4	2177 G
26	2.5	2177 G
27	2.6	3086 G
28	2.7	2177 G
29	2.8	1950 G
30	2.9	2177 G
31	3	2290 G
32	3.1	2177 G
33	3.2	2063 G

AVERAGE 2294.031

M. Jha
06/3/25
JE

06/03/25
AE

Executive Engineer
Rural Works Department
Works Division Chandaha (Pune)

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	UUV	TEGORY ROAD	IRI	Latitude ongitude	Event
6/3/25	12:43:47	98	0.1	160	20.2	1600	1950 G		2.74	25.73372	87.1782 Normal
6/3/25	12:44:22	98	0.1	180	20.2	1800	2177 G		3.02	25.73382	87.17721 Normal
6/3/25	12:45:0	98	0.1	180	20.2	1800	2177 G		3.02	25.73392	87.17626 Normal
6/3/25	12:45:33	98	0.1	260	20.2	2600	3086 G		4.13	25.73398	87.1753 Normal
6/3/25	12:46:8	98	0.1	160	20.2	1600	1950 G		2.74	25.73414	87.17429 Normal
6/3/25	12:46:8	98	0.1	180	20.2	1800	2177 G		3.02	25.73412	87.17332 Normal
6/3/25	12:46:43	98	0.1	180	20.2	1800	2177 G		3.02	25.73413	87.17237 Normal
6/3/25	12:47:17	98	0.1	140	20.1	1400	1722 G		2.45	25.73419	87.17143 Normal
6/3/25	12:47:17	98	0.1	160	20.2	1600	1950 G		2.74	25.73422	87.17045 Normal
6/3/25	12:48:0	98	0.1	290	10.1	2900	3426 G		4.53	25.73418	87.16948 Speed Breaker
6/3/25	12:48:0	98	0.1	140	20.2	1400	1722 G		2.45	25.73406	87.16854 Normal
6/3/25	12:48:28	98	0.1	270	20.2	2700	3199 G		4.26	25.7339	87.16759 Normal
6/3/25	12:48:28	98	0.1	310	20.2	3100	3654 G		4.8	25.73375	87.2 Normal
6/3/25	12:49:3	98	0.1	180	20.2	1800	2177 G		3.02	25.73384	87.16564 Normal
6/3/25	12:49:3	98	0.1	230	20.2	2300	2745 G		3.72	25.73379	87.16468 Normal
6/3/25	12:49:38	98	0.1	150	20.2	1500	1836 G		2.6	25.73382	87.16372 Normal
6/3/25	12:49:38	98	0.1	190	20.2	1900	2290 G		3.16	25.7339	87.16271 Normal
6/3/25	12:50:0	98	0.1	160	20.2	1600	1950 G		2.74	25.73414	87.16177 Normal
6/3/25	12:50:14	98	0.1	160	20.2	1600	1950 G		2.74	25.73439	87.16088 Normal
6/3/25	12:50:14	98	0.1	190	20.2	1900	2290 G		3.16	25.73473	87.15995 Normal
6/3/25	12:50:49	98	0.1	140	20.2	1400	1722 G		2.45	25.73487	87.15894 Normal
6/3/25	12:51:0	98	0.1	190	20.2	1900	2290 G		3.16	25.73509	87.15806 Normal
6/3/25	12:51:0	98	0.1	180	20.2	1800	2177 G		3.44	25.73556	87.15717 Normal
6/3/25	12:52:0	98	0.1	180	20.2	1800	2177 G		3.02	25.73596	87.15623 Normal
6/3/25	12:52:0	98	0.1	260	20.2	2600	3086 G		3.02	25.7363	87.15539 Normal
6/3/25	12:53:10	98	0.1	180	20.2	1800	2177 G		4.13	25.73673	87.15453 Normal
6/3/25	12:54:0	98	0.1	160	20.2	1600	1950 G		3.02	25.73725	87.15379 Normal
6/3/25	12:54:21	98	0.1	180	20.2	1800	2177 G		2.74	25.73799	87.15322 Normal
6/3/25	12:54:21	98	0.1	190	20.2	1900	2290 G		3.02	25.73863	87.15253 Normal
6/3/25	12:55:0	98	0.1	180	20.2	1800	2177 G		3.16	25.73926	87.15194 Normal
6/3/25	12:55:0	98	0.1	170	10.1	1700	2063 G		3.02	25.7397	87.15103 Normal
6/3/25	12:55:0	98	0.1	170	10.1	1700	2063 G		2.88	25.73993	87.15012 Normal
								AVERAGE	2294.031		

$$Y = 0 \cdot X^2 + 1.135 \cdot X + 132.5$$

$$X = 3800$$


$$Y = 4449$$

(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001

[Signature]
Executive Engineer
Rural Works Department
Works Division Chaudhara (Puneal)

[Signature]
06/03/25
JC
26/03/25
AR

File : C:\Users\abhig\Desktop\bump integator\6th march\06031322.Xls, Section No. :98, Eqn : $Y = 0 * X^2 + 1.136$
 Name of Customer : Rohit Raj. Name of Work/ Road : Dhamdaha kerosin tel dipu to chandrahi satsang bhawan, Lab



MD 06/3/25
 SE

06/03/25
 #K<

Executive Engineer
 Rural Works Department
 Works Division Chanddaha (Purnea)


कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल धमदाहा, पूर्णियाँ।


ई0मेल0आई0डी0-eerwddhamdaha@gmail.com

प्रमाणित किया जाता है कि Dhamdaha Kerosin Tel Dipu to Chandrahi Satsang Bhawan का सभी अवयवों की जाँच शत प्रतिशत कनीय अभियंता द्वारा किया गया है। सहायक अभियंता द्वारा सभी अवयवों की 50 प्रतिशत से अधिक जाँच किया गया है। अधोहस्ताक्षरी द्वारा 10 प्रतिशत अवयवों की जाँच की गई है।


09/03/25

कनीय अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रशाखा-धमदाहा।


सहायक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, धमदाहा।


कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, धमदाहा।