

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल दरभंगा-2

Mail ID:-rwdeedbg2@gmail.com

पत्रांक 455. (330)

दिनांक 07/03/2025

प्रेषक,

ई0 अवधेश कुमार,
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्र0, दरभंगा-2

सेवा में,

नोडल पदाधिकारी,
(3054-एम0आर0)
ग्रामीण कार्य विभाग,
बिहार, पटना।


विषय:- शीर्ष-3054 (नई अनुरक्षण नीति-2018) अन्तर्गत पूर्ण किये गये पथों में आवंटन माँग हेतु अधियाचना पत्र समर्पित करने के संबंध में।

महाशय,
उपर्युक्त विषयक के संबंध में गैर योजना मद शीर्ष-3054 (नई अनुरक्षण नीति-2018) अन्तर्गत पूर्ण किये गये पथ में आवंटन माँग हेतु राशि की अधियाचना विहित प्रपत्र तैयार कर समर्पित की जा रही है।

अतः श्रीमान् से अनुरोध है कि रु0 227.830 लाख (कुल दो करोड़ सताईस लाख तेरासी हजार रुपये) मात्र रुपये का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:- यथोक्त।

विश्वासभाजन



कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्र0, दरभंगा-2


7.3.25

Requisition Fromat for Scheme Head- MR(3054) under Bihar Rural Road Maintenance policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- RWD Works Division Darbhanga-2

B-2																			
Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (in Lakh)	up to date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks	
					Length (In Km)	Amount of (In Lakh)	Initial Rectification with Surface Renewal (In Lakh)	5 Years Routine Maintenance (in Lakh)											
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	MR-N/23-24 Darbhanga- 2/11	Tatila to Gautam Kund RCD Road via Naranchh	619931909676	Lt. No-1086 Dt.-01.03.24	3.450	209.6309	143.22707	17.70770	09/MBD/2024-25 Dt.11.11.2024	10.08.2025	Surface Completed.	2893.20	25mm	5	0.00	0.00	143.120	कार्य पूर्ण	
2	MR-N/23-24 Darbhanga- 2/11	Bharnarpura REO Road to Mahuli Barhi Tola	31909312020	Lt. No-6515 Dt.-26.12.23	1.89	128.72	84.75568	10.15985	10/MBD/2024-25 Dt.11.11.2024	10.08.2025	Surface Completed.	2882.00	25mm	5	0.00	0.00	84.710	कार्य पूर्ण	
कुल अभियानित राशि																		227.830	राशि I

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed.
2. Up to date Physical Progress has been uploaded in MIS


 Executive Engineer
 RWD Works Division Darbhanga-2
 11.03.25

FORM GFR 19-A

(See Government of India's Decision (1) below Rule- 150)

Form of Utilisation Certificate up to the month of March-2025

Head 3054 Account for M.R (New Maintenance Policy-2018) Yojna. Year 2024-25


PIU Darbhanga-2


Sl. No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Maintenance Account for Head 3054 Account for MR R (New Maintenance Policy-2018) Yojna	Additional CEO-cum- Secretary Patna. Letter No-12 We Date-07.02.2025	Rs. 4356.60876	Certified that out of Rs 4356.60876 lacs received during the years 2024-25 in favour of Ex. Engineer RWD work division Darbhanga-2 a sum of Rs 4320.6648 lacs has been utilized for the purpose of Maintenance Account for Head 3054 M.R (New Maintenance Policy-2018) Schemes as given in the margin for which it was sanctioned and that the balance of Rs 35.94393 lacs remaining unutilized at the end of the period under.
	Total		4356.60876	

2. Certified that I have satisfied myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Constructions materials have tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer
- All other codal formalities have been observed.


D. A. O.
R.W.D. Works Division
Darbhanga-2


Executive engineer,
R.W.D. Works Division
Darbhanga-2

7.3.25

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल दरभंगा-2

प्रमाण-पत्र

विभागीय आदेशानुसार सत्यापित किया जाता है कि शीर्ष 3054 (नई अनुरक्षण नीति-2018) अन्तर्गत Tataila to Gautam Kund RCD Road via Narauchh तक पथ मरम्मत कार्य की जाँच 100 प्रतिशत संबंधित कनीय अभियंता, 50 प्रतिशत संबंधित सहायक अभियंता एवं 10 प्रतिशत कार्यपालक अभियंता द्वारा कर लिया गया है।

Md. E. / 03/03/25

कनीय अभियंता,
IS

N. K. / 03/03/25

सहायक अभियंता

03/03/25

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्र0, दरभंगा-2

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल दरभंगा-2

प्रमाण-पत्र


विभागीय आदेशानुसार सत्यापित किया जाता है कि शीर्ष 3054 (नई
अनुरक्षण नीति-2018) अन्तर्गत Bharmarpura REO Road to Mahuli Barhi Tola तक
पथ मरम्मत कार्य की जाँच 100 प्रतिशत संबंधित कनीय अभियंता, 50 प्रतिशत
संबंधित सहायक अभियंता एवं 10 प्रतिशत कार्यपालक अभियंता द्वारा कर लिया
गया है।

Md. E. Karmy
03/03/25

कनीय अभियंता,

Nikhil
03/03/25

सहायक अभियंता


03/03/25

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्र0, दरभंगा-2

Name of Road :- Bharmarpura REO Road to Mahuli Barhi Tola

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	EGORY ROAD	Latitude	Longitude	Event
3/3/25	8:37:35	12	0.1	380	0	3800	3716	G	26.3571	85.7744	Normal
3/3/25	8:38:0	12	0.1	320	20.2	3200	3220	G	26.3579	85.7747	Normal
3/3/25	8:38:11	12	0.1	290	20.2	2900	2972	G	26.3587	85.7752	Normal
3/3/25	8:38:11	12	0.1	260	20.2	2600	2724	G	26.3595	85.7756	Normal
3/3/25	8:38:46	12	0.1	300	10.1	3000	3055	G	26.3604	85.7762	Normal
3/3/25	8:39:0	12	0.1	240	20.2	2400	2559	G	26.3211	85.7769	Normal
3/3/25	8:39:0	12	0.1	320	20.2	3200	3220	G	26.3628	85.7772	Normal
3/3/25	8:39:21	12	0.1	270	10.1	2700	2807	G	26.3637	85.7771	Normal
3/3/25	8:40:0	12	0.1	350	10.1	3500	3468	G	26.3645	85.7773	Normal
3/3/25	8:40:0	12	0.1	320	20.2	3200	3220	G	26.3654	85.7776	Normal
3/3/25	8:40:0	12	0.1	230	30.3	2300	2476	G	26.3661	85.7779	Normal
3/3/25	8:40:32	12	0.1	250	20.2	2500	2641	G	26.3669	85.7781	Normal
3/3/25	8:40:32	12	0.1	280	20.2	2800	2889	G	26.3679	85.7782	Normal
3/3/25	8:41:7	12	0.1	260	20.2	2600	2724	G	26.3686	85.7777	Normal
3/3/25	8:41:7	12	0.1	310	10.1	3100	3137	G	26.3692	85.7771	Normal
3/3/25	8:41:42	12	0.1	260	20.2	2600	2724	G	26.3695	85.7761	Normal
3/3/25	8:42:0	12	0.1	280	20.2	2800	2889	G	26.3699	85.7754	Normal
3/3/25	8:42:18	12	0.1	250	10.1	2500	2641	G	26.3709	85.7741	Normal
3/3/25	8:46:23	12	0.09	120	20.2	1333	1676	G	26.3702	85.7743	Normal
Average IRI							2882.00				

$$Y = 0 * X^2 + 0.827 * X + 574.3$$

$$X = 1333$$

$$Y = 1676$$

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

3/3/25

Md. E. K. 03/03/25

Nikhil 02/03/25

Executive Engineer
R.W.D.(W) Division
Darbhanga-2

Name of Customer : Hari Om Enterprises Prop Vikash
 Name of Work/ Road : Bharmapura REO Road to Mahu
 Lab Job number : 12
 Date : 03-03-2025
 Section No. : 12


Test Date : 03-03-2025
 Road Name : Bharmapura REO Road to Mahu
 Machine No : 477
 Road Type : (R) RURAL ROAD
 Start S No :
 Start E No :
 Side :
 Interval :
 Weather :
 UV Range : 576 To 5000 1000 mm/km
 Start Location :
 Dist Range : 0 To 2 0.1 = 1000 m
 End Location :
 Equation : $Y = 0 * X^2 + 0.827 * X + 574.3$

Print

Generate Report and Graph

Redraw Graph

Map View



Spamji
 2/3/25

Md. Ekram
 03/03/25

Nikhil
 03/03/25

(Signature)
 7/3/25

Executive Engineer
 R.W.D.(W) Division
 Darbhanga-2

Name of Work :- Tataila to Gautam Kund RCD Road via Narauchh

Date	Time	Section	Length	Bumps	Speed	OR	IRI	REGORY	Latitude	Longitude	Event
No.	in km	in mm	Rate	mm/km	mm/km	ROAD					
3/3/25	16:38:46	14	0.1	300	10.1	3000	3055 G		26.32943	85.79085	Normal
3/3/25	16:39:0	14	0.1	340	20.2	3400	3386 G		26.32873	85.79127	Normal
3/3/25	16:39:0	14	0.1	280	20.2	2800	2889 G		26.32792	85.79172	Normal
3/3/25	16:39:21	14	0.1	270	10.1	2700	2807 G		26.32707	85.79188	Normal
3/3/25	16:40:0	14	0.1	350	10.1	3500	3468 G		26.3262	85.79199	Normal
3/3/25	16:40:0	14	0.1	260	20.2	2600	2724 G		26.32523	85.79204	Normal
3/3/25	16:40:0	14	0.1	240	30.3	2400	2559 G		26.32476	85.7926	Normal
3/3/25	16:40:32	14	0.1	260	20.2	2600	2724 G		26.32467	85.79336	Normal
3/3/25	16:40:32	14	0.1	250	20.2	2500	2641 G		26.32473	85.79465	Normal
3/3/25	16:41:7	14	0.1	270	20.2	2700	2807 G		26.32487	85.79536	Normal
3/3/25	16:41:7	14	0.1	310	10.1	3100	3137 G		26.32493	85.79656	Normal
3/3/25	16:41:42	14	0.1	280	20.2	2800	2889 G		26.32514	85.79735	Normal
3/3/25	16:42:0	14	0.1	270	20.2	2700	2807 G		26.32547	85.79819	Normal
3/3/25	16:42:18	14	0.1	260	10.1	2600	2724 G		26.32625	85.7986	Normal
3/3/25	16:42:18	14	0.1	250	30.3	2500	2641 G		26.32699	85.79921	Normal
3/3/25	16:43:0	14	0.1	280	20.2	2800	2889 G		26.32725	85.79974	Normal
3/3/25	16:43:0	14	0.1	270	20.2	2700	2807 G		26.32699	85.80081	Normal
3/3/25	16:43:28	14	0.1	250	20.2	2500	2641 G		26.32695	85.80139	Normal
3/3/25	16:43:28	14	0.1	260	20.2	2600	2724 G		26.32678	85.80234	Normal
3/3/25	16:44:1	14	0.1	290	20.2	2900	2972 G		26.3256	85.80246	Normal
3/3/25	16:44:1	14	0.1	320	10.1	3200	3220 G		26.32512	85.80323	Normal
3/3/25	16:44:37	14	0.1	260	20.2	2600	2724 G		26.32467	85.80405	Normal
3/3/25	16:44:37	14	0.1	310	20.2	3100	3137 G		26.32429	85.80453	Normal
3/3/25	16:45:12	14	0.1	250	10.1	2500	2641 G		26.32368	85.80545	Normal
3/3/25	16:45:12	14	0.1	290	10.1	2900	2972 G		26.32326	85.80643	Normal
3/3/25	16:45:47	14	0.1	380	20.2	3800	3716 G		26.32314	85.80739	Normal
3/3/25	16:46:0	14	0.1	250	20.2	2500	2641 G		26.32293	85.80818	Normal
3/3/25	16:46:23	14	0.1	310	10.1	3100	3137 G		26.32352	85.8089	Normal
3/3/25	16:47:0	14	0.1	300	10.1	3000	3055 G		26.32313	85.80983	Normal
3/3/25	16:47:13	14	0.1	240	20.2	2400	2559 G		26.32243	85.80983	Normal
3/3/25	16:47:13	14	0.1	250	20.2	2500	2641 G		26.32204	85.81013	Normal
3/3/25	16:47:46	14	0.1	270	10.1	2700	2807 G		26.32188	85.81091	Normal
3/3/25	16:48:0	14	0.1	350	10.1	3500	3468 G		26.32261	85.81144	Normal
3/3/25	16:48:28	14	0.1	320	20.2	3200	3220 G		26.3224	85.81234	Normal
3/3/25	16:48:28	14	0.051	90	30.3	1765	2033 G		26.32201	85.81331	Normal
Average IRI											2893.2

$$Y = 0 * X^2 + 0.827 * X + 574.3$$

$$X = 1765$$

$$Y = 2033$$

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

Md. S. K. M. 03/03/25

Nilesh 03/03/25

Executive Engineer
R.W.D.(W) Division
Darbhanga-2

03/03/25

Name of Customer : Santosh Kumar Singh
 Name of Work/ Road : Tatalla to Gauram Kund RCD R
 Lab Job number : 14
 Date : 03-03-2025
 Section No. : 14


Test Date : 03-03-2025 Road Name : Tatalla to Gauram Kund RCD R
 Machine No : 427 Road Type : (R) RURAL ROAD
 Start S No : Side : Interval
 Start E No :
 Weather : UV Range : 1833 To 5000 1000 mm/km
 Start Location : Dist Range : 0 To 15 01 * 1000 m
 End Location : Equation : $Y = 0 * X^2 + 0.627 * X + 574.3$

Print

Generate Report and Graph

Redraw Graph

Map View



Spriff
3/3/25

Md. E. K. S.
03/03/25

Nikhil
03/03/25
NE

Wazir
7/3/25
 Executive Engineer
 R.W.D.(W) Division
 Darbhanga-2