

MCISY - L027 to Kanna .

SC Ag No - 58230/19-20

Measurement Book

Schedule XLV-Form No. 134

Shergathi

DIVISION

Dobhi

SUB-DIVISION

MB No - 1138

Agay Kumar

3rd Year Maintenance bid

47

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - 1027 P/KAPMA					
Agency - A Jay Kumar					
Ass H. - 58 SBP/13-20					
Item ① Restoration of Rainchys					
	14	5.10	1.10	0.30	✓ 23.561
	12	4.80	1.15	0.25	✓ 16.561
	13	4.10	1.20	0.35	✓ 19.181
	11	3.90	1.10	0.30	✓ 14.151
	12	6.20	1.20	0.25	✓ 22.321
	10	6.50	1.15	0.30	✓ 22.421
	11	5.80	1.15	0.30	✓ 22.011
	10	5.60	1.25	0.30	✓ 21.001
					✓ 161.21
Item ② Matching up of Boms/					
Shy 141					
	15	6.10	1.20		✓ 109.801
	12	5.60	1.10		✓ 73.921
	11	5.40	1.15		✓ 68.311
	10	4.80	1.20		✓ 57.601
	14	6.50	1.25		✓ 113.751
	13	5.90	1.20		✓ 92.041
	12	4.60	1.15		✓ 63.481
	12	6.30	1.25		✓ 94.501
	10	6.90	1.20		✓ 82.811
	12	5.60	1.20		✓ 80.641

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	12	5.10	1.10		$= 57.32 \text{ m}^2$
					$\checkmark 904.16 \text{ m}^2$
				Lint -	$\checkmark 903.26 \text{ m}^2$
item (3)	Repair of Potholes filled with 2525				
	5	0.325	0.30		$= 0.48 \text{ m}^2$
item (4)	Pavement repair over Bituminous Surface				
	10	2.10	1.20		$= 25.2 \text{ m}^2$
	11	1.50	1.10		$= 18.15 \text{ m}^2$
	12	1.80	1.30		$= 28.08 \text{ m}^2$
	10	2.50	0.90		$= 22.5 \text{ m}^2$
	11	3.10	1.30		$= 44.30 \text{ m}^2$
	9	2.40	0.90		$= 19.44 \text{ m}^2$
					$\checkmark 157.67 \text{ m}^2$
item (5)	Maintenance of C.D works H.P culvert				
					$\checkmark 3 \text{ No}$
item (6)	Maintenance of slab culvert				
					$\checkmark 2 \text{ No}$
item (7)	Maintenance of Road sign				
					$\checkmark 0.3410 \text{ m}$
item (8)	Maintenance of 200mm and 150mm slope				
					$\checkmark 0.41 \text{ m}$
item (9)	Cutting of branches of Tree and shrubs				
					$\checkmark 14 \text{ No}$
item (10)	Cutting of shrubs for road way				
					$\checkmark 2290 = 2290 \text{ m}$

Continuation

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4/15.5011) Paved repair over irregular surface					
V.T.M.B.P.No. - (48)					
Item no (4) - 152.62 m ²					
Q 152.62 x 58/m ² - 42662 =					
(5/15.21) Maintenance of C.D works H.P culvert					
V.T.M.B.P.No. - (48)					
Item no (5) - 3 Hk					
Q 1112.00/Hk - 33513 =					
(6/15.71) Maintenance of C.D works slab culvert					
V.T.M.B.P.No. - (48)					
Item no (6) - 2 Hk					
Q 2309.03/Hk - 4618 =					
(7/15.9) Maintenance of Road side					
V.T.M.B.P.No. - (48)					
Item no (7) - 0.24 Hk					
Q 7024.51/Hk - 365 =					
(8/15.11) Maintenance of road and 100 stone					
V.T.M.B.P.No. - (48)					
Item no (8) - 0.41 Hk					
Q 657.71/Hk - 270 =					
(9/15.12iv) Cutting of branches of tree and shrubs					
N.T.M.B.P.No. - (48)					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	item (9)	14	11		
	Q	106.5	11		1491.2
(1/15-12/11)	cutting of surfs from road way				
	V.T.M.B. P.N.	48			
	item (10)	2290	11		
	Q	6.5	4/11		14972.2
(1/15-12/11)	Trimming of grass and weeds				
	V.T.M.B. P.N.	48			
	item (11)	1162			
	Q	2.18	1/12		2833.2
(12/15-13)	whitewashing of post and rail				
	V.T.M.B. P.N.	48			
	item (12)	8236			
	Q	16.4	1/12		1438.2
					1,90,514.2
	10310% below C-1				19051.2
					1,71,463.2
					129209.2
					bluffs
					15/02/24
					A-E
					C/S Page no- 44
					1200 year mant
					Allotment received from
					BRRDA vide Ltr no- 90WF
					dt- 17/10/2024 c/no- 12
					By CFMS Amt- 129209.2