

5th Year Maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
r/w- Maint. of Road from To 4 Inerua to Lucina Braham Station under B They. Agency- Sri Guddu Kumar Varma A. No- 18/2019-2020 Date of completion- 03/02/2020 Actual completion- 24/01/2020 Date of entry - 11.02.2025						
Record Entry.						

① Restoration of road

cut - 00 -

$$12 \times 4.40 \times 1.00 \times 0.80 = 15.84$$

$$16 \times 3.90 \times 1.10 \times 0.80 = 20.59$$

$$9 \times 4.60 \times 1.05 \times 0.80 = 13.04$$

$$8 \times 4.90 \times 0.95 \times 0.80 = 11.17$$

$$7 \times 5.30 \times 0.90 \times 0.80 = 10.02$$

$$8 \times 5.30 \times 0.80 \times 0.80 = 10.18$$

$$80.84 \text{ m}^3$$

Limit

$$80.19 \text{ m}^3$$

② Maint. of Earthen

Shoulder - 00 -

$$2 \times 9 \times 5.60 \times 0.90 = 90.72$$

$$2 \times 8 \times 4.90 \times 1.10 = 86.24$$

$$2 \times 6 \times 4.50 \times 0.80 = 43.20$$

Continuation



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
@ 100.71 / each					804.00
⑦ Trimming of grass & weeds					
1448.79 m ² wide					
@ 2.08 / m ²					3003.00
⑧ White washing of two coat parapet walls					
29.52 m ² wide					
@ 12.74 / m ²					406.00
Total =					60194.00

Less @ 0.02 m. Rebar. = 12.00
Total = 60182.00

[Signature]
11/2/25
NE

Material used:—

Earthwork = $\frac{80.19}{2} = 40.095 \text{ m}^3$

[Signature]
11/2/25
NE

Continuation