

# 2nd year Maintenance Bill.

46

Sch. XLV-Form No. 134

| Particulars                                                                           | Details of actual measurement |    |    |       | Contents of area |
|---------------------------------------------------------------------------------------|-------------------------------|----|----|-------|------------------|
|                                                                                       | No.                           | L. | B. | D.    |                  |
| Work: Maint. of Road from                                                             |                               |    |    |       |                  |
| Arwai Purbhi PMSY                                                                     |                               |    |    |       |                  |
| Sadak to Bhumi Sharma                                                                 |                               |    |    |       |                  |
| to la (Purbhi Kherho)                                                                 |                               |    |    |       |                  |
| Tak-Under-MMSY-Se.                                                                    |                               |    |    |       |                  |
| Agency: Satyam Kumar                                                                  |                               |    |    |       |                  |
| Appr. No. - 63505/2020-21                                                             |                               |    |    |       |                  |
| D.O. Start - 17.08.2020                                                               |                               |    |    |       |                  |
| A.D.O. Comp. - 06.08.2022                                                             |                               |    |    |       |                  |
| ① Restoration of soil Cuts                                                            |                               |    |    |       |                  |
| With Soil - --- C12                                                                   |                               |    |    |       |                  |
| $2 \times 350.0 \times 1.125 \times 1.25 \times 0.3 \times 0.072 = 21.26 \text{ m}^3$ |                               |    |    |       |                  |
| ② Making up of Berms/                                                                 |                               |    |    |       |                  |
| Shoulders - --- C12                                                                   |                               |    |    |       |                  |
| $2 \times 580.0 \times 1.125 \times 1.25 \times 0.12 = 195.75 \text{ m}^3$            |                               |    |    |       |                  |
| ③ Patch repair over Bituminous                                                        |                               |    |    |       |                  |
| Surface - --- C12                                                                     |                               |    |    |       |                  |
| $350.0 \times 3.75 \times 1.25 \times 0.01 = 16.406 \text{ m}^2$                      |                               |    |    |       |                  |
| ④ Maintenance of CD work                                                              |                               |    |    |       |                  |
| in HP. Culvert - --- C12                                                              |                               |    |    |       |                  |
|                                                                                       |                               |    |    | 1.0 m |                  |
| ⑤ Maintenance of Road                                                                 |                               |    |    |       |                  |
| Signs - --- C12                                                                       |                               |    |    |       |                  |
| Continuation                                                                          |                               |    |    |       | 0.07 km          |

Scanned with CamScanner