

3rd Year maintenance

67

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of owner - mangeshkari					
P.A. - Co-operative Garden					
To madhav chowk tank					
Agency - S. J. Tenders & tenders					
Agno - 101 (STD) money / 00-21					
Actual D.O. - comp - 21.03.24					
Date of measur -					

(1) Restoration of rain cuts

$$2 \times 2 \times 30.0 \times 1.0 \times 0.30 = 36.0$$

$$2 \times 22.5 \times 1.05 \times 0.30 = 14.17$$

$$2 \times 14.50 \times 0.90 \times 0.30 = 7.88$$

58.05

(2) making up of earthy
shoulder

$$2 \times 5 \times 30.0 \times 0.90 = 270.0$$

$$2 \times 3 \times 30.0 \times 1.05 = 189.0$$

$$2 \times 22.25 \times 1.10 = 49.50$$

508.50

1 mdt - 507.94

m²

(3) Repair of pot hole

$$2 \times 5 \times 1.05 \times 1.20 = 12.55$$

$$2 \times 11.35 \times 0.90 = 20.43$$

$$2 \times 3 \times 2 \times 3.30 \times 1.30 = 57.72$$

Continuation

57.72

Lmt - 57.66

m²

Sch. XLV-Form No. 134

71

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) 735 m ² 108104 =					
11/14 Road marking with bit applications on RCC.					
94.0m ² videtm B.P.C (69)					
(a) 820 = 571/2 - 77135.					
12/15 maintenance of already planted trees					
82nes videtm 8.20. (69)					
(a) 561 = 0/000 - 46002 =					
0.12 km - 77135 327152					
add 131.605716 - 42530 =					
369682 =					
Less 10% as pro agnt - 369682 =					
Road has maintenance 332714 =					
as per specification					
Q.M. 15/2 31.01.2025 P.R.					
(a) /					
Ansde 10/03/25 EE					