

Chhanta Devi

NFB/AD 3

Schedule XIV-Form No. 134

Makhdumpur Bhamarua Sadak Via Taru Bazaar

E. E. R. W.D. (C) DIVISION
G19X19

A. E. R. W.D. (C) SUB-DIVISION
W19Z1R61ANJ

MEASUREMENT BOOK

~~P1667453~~

2823

Page 1d - ~~P1667453~~ P1667453 PT0076118

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Conten of are
	No.	L.	B.	D.	
Ist on A/c Bill					
Same of work: Const of rural road for Makhampur Bhagausa Sade via Garwa Bhagausa Sinsar Agar - bari allina pakor To Baluga Ghat Garwa Tak under NABARD Geny: Chaita Devi Tenth - 74/NABARD/SBD/2019-20 Gen. 17.12.19 Loc: 16.12.2020 Date of Measurement: 24.4.20					
(i) Setting out of working BM Pillar posts - 03 nos					
(ii) Fixing ref pillar 10 nos					
(2) Clearing & grubbing of road (2m) dual					
$2 \times 20 \times 30.4 \times 3.50m = 4200.4 m^2$					
$2 \times 20 \times 30.4 \times 3.50m = 4200.4 m^2$					
$2 \times 20 \times 30.4 \times 3.50m = 4200.4 m^2$					
$2 \times 20 \times 30.4 \times 3.50m = 4200.4 m^2$					
$2 \times 3 \times 30.4 \times 3.50 = 630.4 m^2$					
$2 \times 1 \times 10.4 \times 3.50 = 70.4 m^2$					
					17500.4 m^2
Continuation of 1.75 Hect					

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - 4th Year Maint of road from Makdumpur Bazar to Sadak via Taswa Bazar, Sikan, Aganbari Alhara Pakar to Basu (Plot Trwq					
Agency - Chinta devi					
Aggt No - 74/NABARD/SE0/2017-20					
Date - 17.10.19					
ADC - 11.01.21					
(1) Restoration of road cuts					
			138.21	M ³	
(2) Making up of Broomy shoulder.					
			1054.69	M ²	
(3) Repair of pot holes					
			168.75	M ³	
(4) Patch repair over bituminous.					
			168.75	M ³	
(5) Maint of c/d works					
			8.00	No	
(6) Cutting of branches of trees.					
			4.00	No	
			12113	12/01/25	

Continuation

Handwritten signature
12/01/25
TE

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		Abstract of Cont			
(1)		Restoration of main cutty.			
P/57		128.2143			
		C	379 = 59	R = 52462 = 00	
(2)		Molding up of Berry			
P/57		1054.6942			
		C	56 = 81	R = 59917 = 00	
(3)		Repair of pot hole			
P/57		168.7543			
		C	184 = 70	R = 31169 = 00	
(4)		Patch repair over bituminous.			
P/57		168.7542			
		C	162 = 51	R = 27423 = 00	
(5)		Height of C/D Works			
P/57		8.0010			
		C	1109 = 80	R = 8892 = 00	
(6)		Cutting of branches of trees.			
P/57		4.0010			
		C	106 = 12	R = 424 = 00	
				R = 180217 = 00	
				R = 18021 = 00	
				R = 16296 = 00	
12 below	10% (-)				
11/01/15	14/01/15				
10/01/15	14/01/15				
Continuation					

Continuation