

SC
Schedule XLV-Form No. 134

SH 76 Toivenigay-Jadiya Se Jawahas
Sak ghar hoti huye ~~Abu~~ **DIVISION** ~~holitak~~

SUB-DIVISION

Bz' bhas kumar jha.

Measurement Book

Birash kumar M.B. No - 629
Jha

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year maintenance Bill					
Abstract of cost					
Name of road: — Construction					
of road from SH 76					
Taivenigany to Jawahar					
Sah hotz hue Thakur					
Tola Tax					
Ass No — 136/SBD/MMGSY/ 18-19					
Agency: — Bibhash kr. Jha					
Actual Date of completion					
— 20.08.2020					

Item ① Restoration of rain culb					
15.1					
16.20 m ³ =	3	30	0.60	0.30	
9.0 m ³ =	2	30	0.50	0.30	
3.0 m ³ =	1	20	0.50	0.30	
28.20 m ³ @ Rs 398.45/m ³					113.00
					= Rs 112 36.00
Item ② Maintenance of					
15.2 earthen shoulder -.					
63 m ² =	3	30	0.70		
36 m ² =	2	30	0.60		
48 m ² =	2	30	0.80		
110 =	1	20	0.50		
157 m ² @ Rs 54.16/m ²					

Continuation = Rs 8503.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item ③ Repair of Pot holes					
15-3(1) felled with 75 mm					
Bm -do					
0.50 m ² =	4	3.0	0.60	0.075	
1.35 m ² =	6	2.50	1.2	0.075	
0.217 m ² =	1	2.90	1.0	0.075	
21107 m ² @ Rs 10210.17 / m ²					
					=Rs 21513.00
Item ④ Patch repair over					
15-3(11) pot holes -do					
7.20 m ² =	4	3.0	0.60	0.90	
18.00 m ² =	6	2.50	1.20		
2.90 m ² =	1	2.90	1.0	0.00	
25.10 m ² @ 217.67 / m ²					
					=Rs 6117.00
Item ⑤ Maintenance of					
15-7(1) HPC -do					
1 no @ Rs 1131.64 each					
					=Rs 1132.00
Item ⑥ cutting of branches					
15-12(1) of trees					
1 no @ 118.23 each					
					=Rs 118.00
Item ⑦ cutting of shrubs					
15-12(11) from road way					
4 no @ Rs 6.60 each					
					=Rs 26.00
Total Rs					48645.00

Continuation

—c/o

Material statement		
①	Soil	— 28.20 m ³
②	Bitumen	— 0.215 m ³
③	stone chips	— 3.75 m ³
④	Emulsion	— 0.02 m ³

Continuation

Sch. XLV—Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
4th Year maintenance Bill					
Name of road:— Construction of road from SH 76 Triveniganr To Jawahar Sah hok huc Thakur Tola tan.					
Agg no — 136/SBD/MMGSY/2018-19					
Agency: — Bibhash kr. Jha					
Actual Date of completion — 20.08.202					
Date of entry: — 11.08.20					
Item ① Restoration of					
15.1					
rain cul - do					
16.20 m ³ = 3 30 0.60 0.30					
16.20 m ³ = 2 30 0.90 0.30					
32.40 m ³ @ Rs 398.45 / m ³					
= Rs 12910.00					
Item ② Maintenance of					
15.2 earthen shoulder..					
81 m ² = 3 30 0.90					
60 m ² = 2 30 1.0					
36 m ² = 2 30 0.60					
177 m ² @ Rs 54.16 / m ²					
= Rs 9586.00					
Item ③ Repair of pot holes					
15.3 (1) filled with 75 mm BM					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
0.87 m ² =	6	2.15	0.90	0.075	
0.58 m ² =	4	3.25	0.60	0.075	
1.08 m ² =	5	2.90	1.0	0.075	
0.236 m ² =	8	1.75	0.60	0.075	
2.766 m ² @ Rs 10			210.00/m ²		
			= Rs	28	241.00
Item ④ Patch repair over					
15.3(11) Pot holes - do					
11.61 m ² =	6	2.15	0.90		
7.80 m ² =	4	3.25	0.60		
14.50 m ² =	5	2.90	1.0		
3.15 m ² =	3	1.75	0.60		
37.06 m ² @ Rs 217.87/m ²					
			= Rs	8067.00	
Item ⑤ Maintenance of					
15.7(1) Hume Pipe culvert					
1 No @ 1131.64 each					
			= Rs	1132.00	
Item ⑥ Maintenance of					
15.9 road sign do ...					
0.40 km @ Rs 1055.96			610.85/km		
			= Rs	422.00	
Item ⑦ Maintenance of					
15.11 200 m and kilometer					
0.40 km @ Rs 610.85/km					
			= Rs	244.00	

Continuation

①	Soël	—	32.40 W
---	------	---	---------

② Stone metal $\rightarrow 4.06 \text{ m}^3$

③	Bitumen	-	0.292 mT
---	---------	---	----------

④ Emulsion $\rightarrow$ 0.025 mT