

7th Year Main. Bill

45

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NIW - Baligan P.A. Chandpura					
pull to Chandpura paschim					
Char hole.					
Aggr Agency - Radhe Krishna Pvt. Ltd.					
Aggr. No - 101/SBD/MMR57/2019-20					
Actual D.O.C. - 12.12.2020					
Record entry					
① Restoration of Rainwater -					
$2 \times 5 \times 15 \times 0.90 \times 0.30 = 40.50 m^3$					
$7 \times 10 \times 0.95 \times 0.30 = 19.95 "$					
$2 \times 6 \times 15.98 \times 0.85 \times 0.30 = 48.90$					
					$70 = 109.35 m^3$
② Maintenance of earthen shoulders -					
$2 \times 40 \times 30 \times 0.90 = 216.00 m^2$					
$2 \times 5 \times 15 \times 0.85 = 127.50 "$					
$2 \times 7 \times 20.95 \times 0.90 = 263.97 "$					
					$70 = 607.47 m^2$
③ Patch repair on already					
filled pot holes - - -					
$12 \times 1.35 \times 1.00 = 16.20 m^2$					
$15 \times 1.20 \times 1.10 = 19.80 "$					
$22 \times 1.39 \times 1.05 = 32.11 "$					
$4 \times 1.50 \times 1.15 = 6.90 "$					
					$70 = 75.00 m^2$

Continuation

