

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Measure of work: WH-57 hpl					
Shop to Telumi 8489.					
Qty: 800 Swarth Rei					
Appro: 0000 CSY / NDB-68 / 19-20					
Actual Date of Completion: 17-03-21					
① Restoration of 5000 Cnt. - Tse.					
	2x16	30.00	0.60	0.30	172.8
					43
				Total =	172.80
Add 2x12	30.00	0.50	0.30		108.0
				Total =	280.80
② Making up loss of materials Tse					
	2x40	30.00	0.50		1200.00
	2x10	30.00	0.50		300.00
				Total =	1500.00
③ Maintenance of House pipe					
Culverts - Tse.					
				Qty =	$1000.$
				Total =	$1000.$
④ Maintenance of Road 8000 Tse					
				Qty =	4.540
				Total =	4.540
⑤ Maintenance of 2000000000					
Stone - Tse.					
				Qty =	0.681
				Total =	0.681

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B.F	204	199777

(5) Maint of doors & stone

ndel/teron no. (5) rton (5)

Qty = 0.6811 m @ 772.31/m 526 =

(6) Trimming of grass & weeds

ndel/teron no. (6) rton (5)

Qty = 3900.00 m @ 2.16/m 8280

Total = 208583

(-) res/ox. before (-) 20815

Total 187725

10/11/14
A-E

Material Statement

(1) G.W. - 275.81 m³