

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
① Making of Signal boxes road					
② Repairing of Rat holes with W.D.M. gls. 3rd					
③ Patching of Rat holes - d					
④ Maintenance of P. Culvert - d					
⑤ " " Road Signs - d					
⑥ " " 220m and 4. m Shrub - d					
⑦ Cultivation of Trees and Shrubs - d					
⑧ " of Shrubs for road side					
⑨ Painting on parapet walls - d					
⑩ Repairing of B.T. Joints - d					
⑪ " " on Puccina - d					
⑫ all Complaints					
Total Work done by 1.020 km.					

22/12/24
16/12/24
J.C.

16/12/24
16.

Abstract of work

① Repairing of Rat holes - Making of Signal boxes road
Repairing of Rat holes with W.D.M. gls. - Patching of Rat holes with M.S. Gal. Mahul - Maintenance of P. Culvert, Road Signs, 220m and 4m Shrub - Cultivation of Trees and Shrubs - Painting on parapet walls - Repairing of B.T. Joints and Puccina - all Complaints

Continuation

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
Total Work done at side					
T.M. B. By No (8) = 1020 km					
@ 2, 32.220 = 59/km R.					236865 =
					R 236865 =
And G.S.T 12% → + R					28424 =
And Labour Chgs - 1% → + R					2369 =
					Total R 267658 =
Less 10% P.T. below - @ R					26766 =
					Net R - 240892 =

Done
16/12/24
S.E.

Done
16/12/24
S.E.

Material Statement

- ① Earthwork - 96.50 m³
- ② Stone work - 12.50 m³
- ③ Stone Metal - 62.80
- ④ Emul/km - 0.0104 m⁷
- ⑤ Bitum - 0.095 m⁷

Done
16/12/24
S.E.

Continuation