

5th years maintenance

76

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: maintenance of road from (0.57 Chauranagar chaur (from Begha) to Bangal					
TO 9					
2. Name of Agency: mykash Kumar Singh					
3. Agreement No: 69/SAD/201920					
4. Actual dt of completion: 23.02.2020					
—work done—					
① Restoration of drain cuts					
T with soil - eluber					
2x 10.50 x 0.75 x 0.30 = 4.725					
8x 20.60 x 0.74 x 0.30 = 36.585					
7x 10.80 x 0.74 x 0.28 = 15.664					
4x 20.60 x 0.72 x 0.32 = 18.984					
3x 10.58 x 0.75 x 0.30 = 7.141					
2x 10.58 x 0.62 x 0.28 = 2.284					
					Qty = 85.383m ³
					Safety = 85.02m ³
Or maintenance of earthen					
shoulder to - 612					
8x 20.90 x 0.75 = 125.40					
6x 20.85 x 0.72 = 90.072					
5x 20.64 x 0.72 = 74.304					
6x 18.20 x 0.70 = 76.44					
5x 20.72 x 0.73 = 75.628					
2x 21.85 x 0.50 = 21.85					
2x 9.50 x 0.50 = 9.50					
					Qty = 473.194m ³
Continuation					Qty = 472.33m ³

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
check 105m			13.46		123389.00
					126204.00
Qty = 257.60 m ² wide					
1000 page (78)					
① R 7552 53/m					164403.00
					R 293792.00
less 10.0% below C.R.					29379.00
					R 323171.00
					R 264413.00
Done					
23.02.2025					
J.E.					
material statement					
① earth					155.87m ³
② Bitumen 90					485.47kg
③ Stone chips					6.560m ³

Continuation