

Name of work— ¹Constⁿ of road with maintenance work
 from Makana REO Rd Dain to Mahadalit Tola
 Situation of work— Under— Bahadurpur Block.
 Agency by which work is executed— Sri Rajesh Kr. Mandal.
 Date of measurement— At— Barwara Dih Tola.
 No. and date of agreement. 03 SBD/2019-20
 (These four lines should be repeated at the commence-
 ment of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Estimated Cost:-	Rs. 70,84,316.00.				
Agreement Value:-	Rs. 66,58,494.00.				
Rate:-	6.01% Below B.O.C. Rate				
Date of start:-	06.03.2019				
Date of Completion:-	05.12.2019.				
Date of measurement:-	15.06.19				
①	Construction of reference and working benchmark				1.213 KM.
②	Construction of reference pillars/Burgers - danda				1.213M.
③	Clearing and Grubbing road land - danda				
(P)	40	30.00	3.00		= 3600.00m ²
	1	13.00	3.00		= 39.00"
					3639.00m ²
				Say	0.3639 Hect
④	Construction of road embankment with material obtained from borrow pits				
	With a lift of 1.5M				
	transporting to site				
	spreading, grading				
	to required slope and				
	compacting with each 100m.				

Continuation

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) Name of the maintenance of road Marked R 50					
and along to Marked R 50					
2) Agency - Rajeev Kumar Mandal					
3) Date - 03/05/2019-20 (State Survey)					
4) Actual date of work - 03/12/2019					
Item (1) Restoration of road					
7 m x 13 m x 0.95 x 0.45 = 38.90 m ²					
11 m x 9.6 m x 0.8 m x 0.60 = 47.52 m ²					
10 m x 6.0 m x 0.96 x 0.45 = 24.20 m ²					
					110.72 m ²
				1 m	110.16 m ²
Item (2) Repair of Road					
3 m x 11 m x 0.8 = 22.80 m ²					
10 m x 2.7 m x 0.85 = 22.95 m ²					
					550.95 m ²
				1 m	550.80 m ²
Item (3) Repair to pot holes					
5 m x 6.5 m x 1.90 = 62.22 m ²					
1 m x 4.5 m x 1.65 = 7.43 m ²					
4 m x 5.6 m x 1.85 = 41.44 m ²					
4 m x 2.75 m x 1.50 = 16.50 m ²					
					127.59 m ²
				1 m	127.50 m ²
Item (4) Patch repair					
Area under Item (3) -					127.50 m ²

Continuation

Sch. XLV-Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	

Continuation