

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
3rd Year maintenance					
Area of Micee — maintenance of					
Road from Belamagh village to					
Chakdian purab to a mark					
MM 684, Sahan					110
Area — Rakesh Kumar Singh					
Area — 49801/2020-21					
Debit Area — 3.1.2021					
Debit Area — 5.11.2024					
① Restoration of					1380
Rains cut was all					
16 x 15m x 75 x 0.3					20.25 m ³
44 x 15m x 60 x 0.3					10.80
10 x 10m x 60 x 0.3					1.80
					32.85 m ³
2. Making up of Boring					
Shly was all					
10 x 15m x 90 x 0.35					47.25 m ²
4 x 15m x 60 x 0.36					36
					171 m ²
3. Repair of pool house					
filled was some was all					
3 x 3m x 1.50 x 0.75					1.0125 m ³
1 x 2m x 1.5m x 0.75					0.18
					1.1925 m ³

