

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, महनार (वैशाली)

पत्रांक
प्रेषक ,

440 (मउग)

/ महनार / दिनांक :- 11/03/2025

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, महनार

सेवा में,

नोडल पदाधिकारी, MR (3054)
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय :- नई अनुरक्षण निति-2018 MR (3054) के तहत निर्मित पथ की राशि
की अधियाचना पत्र समर्पित करने के संबंध में।

महाशय,

उपरोक्त विषय के संदर्भ में नई अनुरक्षण निति-2018 MR (3054) से
निर्मित पथ के लिए राशि की अधियाचना विहित प्रपत्र में समर्पित की जा रही है।

विदित है कि अधियाचित पथ का कार्य संतोषप्रद है। अधियाचित पथ
में आवंटन देने की कृपा की जाये।

अनु०:-1. अधियाचना विहित प्रपत्र।

विश्वासभाजन

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, महनार

11/3/25

11/3/25

MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)
Name of Works Division. Mahnar

Sl No	Package No	Name of the Road (English)	Project ID as per MIS	Administrative Approval (AA) Letter no Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No & Date	Date Completion as per Agreement	Actual Date of Completion	Value of IRI (In mm/Km)	Thickness of Bitumen Layer / Thickness of PCC (In mm)	Value of Bitumen Content in Percentage/ Grading of concrete	Previous Total Allotted Amount (In Lakh)	Up to Date Expenditure as per MIS	Requisition against work done (in Lakh)	Remarks
					Length (In KM)	Amount of Lakh	Initial Rectification and Surface Renewal (in Lakh)	Five Years Routine Maintenance (In Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/VA/MA H/23/0022	From Birpur Main Road To Main Road Krishna Thakur House	31507713017	24/02/2023	0.880	79.52	67.4074	6.13583	14/MBD/23-24 dt-10/7/2023	09/04/2024	06/04/2024	3249.00	Bitumen-25 mm PCC- 125	Bitumen-5.019 % Grading-M30	61.98023	61.98023	5.00644	
2	RM/VA/MA H/24/0024	Paharpur - Raghupur West	N315077022002	03/01/2024	1.630	213.98	143.87698	5.33107	25/MBD/20-24-25 Dt-18/09/2024	17/06/2025	-	3555.00	PCC- 125	Grading-M30	31.50000	31.50000	75.00000	
3	RM/VA/MA H/24/0004	L054-T04 Nayagaon West to Ganhari (VR16)	31507702047	4/12/2023	0.720	69.49	54.9186	2.68087	03/MBD/20-24-25 13/08/2024	1/5/2025	-	3449.00	PCC- 125	Grading-M30	18.90000	18.90000	31.65100	
4	RM/VA/MA H/24/0018	Lakkar baba astan to southern direction up to h/o chandeshwar mahto via harijan tola under Jurawanpur karari panchayat (Raghupur)	31507601033	4/12/2023	1.000	79.84	54.35945	3.27731	13/MBD/20-24-25 18/09/2024	17/06/2025	-	3116.80	PCC- 125	Grading-M30	0.00000	0.00000	49.50877	
5	RM/VA/MA H/24/0007	PCC Road Chak Singar Near Satydev Singh House To Chaksingar Ghat	31507713013	31/03/2023	0.560	70.16	44.13727	3.38644	04/MBD/MR-3054/2024-25 19/08/2024	18/05/2025	-	3583.00	PCC- 125	Grading-M30	14.00000	14.00000	30.00000	
6	RM/VA/MA H/24/0025	Kalyanpur Rambilas Rai ke Dalan to Musan Toli Masjid Kalyanpur	31507712052	31/03/2023	0.750	70.45	46.93715	5.11988	27/MBD/20-24-25 15/10/2024	14/07/2025	-	3199.25	PCC- 125	Grading-M30	0.00000	0.00000	36.00000	
7	RM/VA/MA H/24/0015	Paharpur PCC Road - Jamindari Ghat	NEA220002704	15/01/2024	5.500	521.327	347.57852	22.77424	18/MBD/20-24-25 Dt-18/09/2024	17/06/2025	-	3562.00	PCC- 125	Grading-M30	336.18875	336.18875	10.79882	

- 1 Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed.
- 2 Up-to-date Physical Progress has been uploaded in MIS


DAO
RWD, Works Division, Mahnar


Executive Engineer
RWD, Works Division, Mahnar

Teal
11/3/25

FORM GFR -19 -A

(see Govt. of India's decision (i) below rule 150)

Form of Utilisation Certificate upto 11.03.2025

Rural Road Maintenance policy-2018

PIU:- R.W.D. Works, Division , Mahnar

Sl. No.	Name of Scheme	Sanction No.& Date with amount (in Rs. Lakh)	Amount Received (in Rs. Lakh)	Particulars
1	2	3	4	5
1	Construction of Road Under Rural Road Maintenance policy-2018	15254.02134	15254.02134	Certified that out of Rs. 15254.02134 Lakh received till date in favour of Ex-Engineer, R.W.D. Works Division, Mahnar a sum of Rs. 15223.32081 Lakh has been utilized for the purpose of Rural Road Maintenance policy-2018 Scheme as given in the margine for which it was sanctioned and that the balance of Rs. 30.70053 Lakh remaining unutilized at the end of the period under the time of completion.
		15254.02134	15254.02134	

- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the propose for which it was sanctioned.

Kind of Checks Exercised :-

- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/Superintending Engineer
- (iii) Construction materials have been tested.
- (iv) Measurments have been recorded in the MB's and test check conducted by the Assistant
- (v) All other codal formalities have overserved


3 Physical Progress Achieved.

- (i) Construction of Bridge Works
- (ii) Construction of Piling Works.


11/3/25
Divisional Account Officer
Rural works Department
Works Division, mahnar


11/03/25
Executive Engineer
Rural works Department
Works Division, mahnar

File :D:\BUMP\Baban Singh\14012025paharpurwest.xlsx, Section No. :90, Eqn : $Y = 0 * X^2 + 0.860 * X + 622.7$
 Name of Customer :Suman Construction_Developer, Name of Work/ Road :Paharpur-Raghopur West, Lab Job number :90



Signature
 14/11/25
 S.C.

Signature
 13/11/25
 S.C.

Name of Contractor :-Suman Construction & Developer Prop Suman Singh
Name of Work :-Paharpur - Raghopur West

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI, TEGORY ROAD	Latitude	Longitude	Event
14/01/25	10: 2: 1	90	0.1	340	10.1	3400	3431 G	25.539847	85.372989	Normal
14/01/25	10: 2: 37	90	0.1	290	10.1	2900	2982 G	25.5397	85.373072	Normal
14/01/25	10: 2: 52	90	0.1	330	10.1	3300	3341 G	25.538308	85.374035	Normal
14/01/25	10: 3: 0	90	0.1	310	10.1	3100	3161 G	25.538311	85.374037	Speed Breaker
14/01/25	10: 3: 13	90	0.1	370	10.1	3700	3700 G	25.538671	85.373653	Normal
14/01/25	10: 3: 35	90	0.1	380	10.1	3800	3790 G	25.539413	85.373324	Normal
14/01/25	10: 3: 45	90	0.1	400	10.1	4000	3969 G	25.541565	85.371607	Normal
14/01/25	10: 3: 58	90	0.1	320	10.1	3200	3251 G	25.541504	85.371555	Speed Breaker
14/01/25	10: 4: 0	90	0.1	390	10.1	3900	3880 G	25.542275	85.371707	Culvert
14/01/25	10: 4: 5	90	0.1	360	10.1	3600	3610 G	25.542572	85.371775	Normal
14/01/25	10: 4: 23	90	0.1	380	10.1	3958	3932 G	25.54217	85.371658	Normal
14/01/25	10: 5: 25	90	0.1	300	10.1	3000	3071 G	25.54197	85.371583	Normal
14/01/25	10: 6: 44	90	0.1	390	10.1	3900	3880 G	25.541827	85.371668	Normal
14/01/25	10: 7: 0	90	0.1	300	10.1	3000	3071 G	25.542274	85.371713	Normal
14/01/25	10: 7: 13	90	0.1	400	10.1	4000	3969 G	25.541814	85.371656	Speed Breaker
14/01/25	10: 7: 38	90	0.1	360	10.1	3600	3610 G	25.54193	85.371673	Normal
14/01/25	10: 7: 55	90	0.031	380	10.1	3800	3790 G	25.539414	85.373323	Normal

IRI Value 3555

$$Y = 0 * X^2 + 0.860 * X + 622.7$$

$$X = 3800$$

$$Y = 3790$$

Good Average Poor
<4000 4001-5000 >5001

14/1/25
14/1/25

15/1/11/25