

2nd year mainfence
Sch. XLV-Form No. 134 60

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Name of work - SHU mandiron

at road for Bhadi

Siman.

Agency :- Sumar construction.

Date of start :- 15/12/2020

Date of Actual Completion :- 03/12/21

Record entry

1. Restoration of drains -

$$1 \times 30.0 \times 0.80 \times 0.30 = 7.20 m^3$$

$$1 \times 22.50 \times 0.90 \times 0.30 = 6.07 m^3$$

$$2 \times 25.10 \times 0.80 \times 0.30 = 12.04 m^3$$

$$25.31 m^3$$

2. Making up of Berma -

$$1 \times 30.0 \times 0.90 = 27.00 m^2$$

$$1 \times 22.50 \times 0.85 = 19.12 m^2$$

$$1 \times 35.0 \times 0.95 = 33.25 m^2$$

$$1 \times 45.50 \times 0.85 = 38.67 m^2$$

$$118.04 m^2$$

3. Mainfence of C/D work
H.P

$$1 \times 2 = 2 m^2$$

4. Mainfence of road sign -

$$0.19 km$$

5. Mainfence of road sign -

$$0.19 km$$

6. Cutting of branch

$$0.19 km$$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			BR	34941.00	
Add for lost @ 12% W				4193.00	
Add for loss @ 1%				349.41	
			R	39184.00	
less from 17.2% G below				6731.04	
			R	32403.00	
Page No. 10/11/24					
7E			AF		CSP
					10/11/24

Major's Statement

~~(1) - 21.14 m³~~

~~Signature~~
~~10/12/24~~
~~9.E~~