

२२६. २२६१६ / अ. २२६१६

BACHHI PASI KE LOHAR To BRAHMAN
7021 Schedule XLV-Form No. 134

BENIOLAR

DIVISION

MANUSY-SC
(MAINTENANCE)

BENIOLAR

SUB-DIVISION

MEASUREMENT BOOK

अभिद कुमा ३१

M.B.N-1599

Abstract / CV
with zero maintenance

Sch. XIV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) Repairing Rain cut					
26.33m ³ CV 7ms R.N 14-15					
Q 398.45/m ² —					Q 30414=
2) Masonry Beam and					
Shower					
435.9m ² CV 7ms R.N 15					
Q 54.16/m ² —					Q 23608=
3) Repair of pot hole					
11m x 12 75 Bm					
5.53m ³ CV 7ms R.N 16					
Q 9869.07/m ² —					Q 54576=
4) Patch repair over pot					
hole with m.s.					
73.88m ² CV 7ms R.N 16					
Q 211.0/m ² —					Q 15589=
5) Maintenance of C.D work					
3N CV 7ms R.N					
Q 1131.64/each —					Q 3335=
					Q 127582=
Less 10% below					Q 12758=
					Q 114824=
40000/-					
112125/-					
72000/-					

Continuation