

1st year maintenance.

20

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/WORK:- main ⁿ of Road from Basghata Reo Sadak To Md. Issa ke Ahaz Hote Hue FWD Laluchowk.					
N/Agency:- Ram Swarth Ray.					
Agg. NO:- MMGSY NDB 68/2019-20					
D.O.S:- 20.03.2020					
D.O.C:- 19.03.2021					
A.D.O.C:-					
Date of measurement					

(1/1)	Restoration of main				
	cuts - do - do - E/I				
	4x	6.00x	0.80x	0.30 =	5.76m ³
	5x	7.00x	0.70x	0.30 =	7.35m ³
	6x	9.00x	0.80x	0.30 =	12.96m ³
	5x	5.00x	0.70x	0.30 =	5.25m ³
	6x	6.00x	0.50x	0.30 =	5.40m ³
	5x	5.00x	0.60x	0.30 =	4.50m ³
				Qty =	41.22m ³
				Limit Qty =	41.01m ³
(2/2)	main of earthen				
	Shoulder - do - do - E/I				
	9x	9.00x	0.60	=	48.60m ²
	8x	8.00x	0.80	=	51.20m ²

Continuation

$$\text{Qty} = 99.80 \text{ m}^2$$

Sch. XLV—Form No. 134

[illegible]

Continuation