

कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, बक्सर

पत्रांक.....५५५ /

बक्सर, दिनांक.....२१.०३.२०२५

प्रेषक:-

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बक्सर।

सेवा में,

नोडल पदाधिकारी,
३०५४ (M.R) कोषांग,
बिहार, पटना।

विषय:-

शीर्ष ३०५४ नई अनुरक्षण नीति-२०१८ अंतर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक कहना है कि विहित प्रपत्र में संलग्न विवरणी के अनुसार शीर्ष Mr 3054 New Maintenance Policy-2018. अन्तर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु राशि की आवश्यकता है।

अतः कार्यहित में अनुरोध है कि उक्त अधियाचित राशि उपलब्ध कराने की कृपा की जाय ताकि कराये जा रहे कार्यों का विपत्र भुगतान किया जा सके।

- अनु०:- (१) अधियाचना प्रपत्र
(२) IRI Value Report
(३) Map
(४) प्रमाण-पत्र।

विश्वासभाजन




२१.३.२५

कार्यपालक अभियन्ता

ग्रा०का०वि०, कार्य प्रमण्डल,

बक्सर


२१.३.२५

FORM GFR 19-A

(See Government of India's Decision (I) below Rule- 150)
Form of Utilization Certificate upto date of 20.03.2025

Name of Scheme :- MR NEW MAINTENANCE POLICY-2018.

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (Rs.In lacs)	Amount Received (Rs.In Lacs)	Particulars
Through C.F.M.S. Received			-	
1	MR NEW MAINTENANCE POLICY 2018.	BF up to 2024-2025 Lt No-02 dt-14.01.2025 <u>12524.36810</u>	12524.36810	Certified that Alltoment Received during the year 2024-2025 Throught C.F.M.S. Rs.12524.36810 lacs of grants-in- favour of Executive Engineer, R.W.D.(W) Division, Buxar. Bihar a sum of Rs.12501.25022 lacs has been utilized for the purpose of MR NEW MAINTENANCE POLICY-2018. schemes as given in the margin for which it was sanctioned and that the balance of Rs.23.11788 lacs remaining unutilized at the end of the period under report.
		Total Rs. =	12524.36810	

- 2 Certified that I have satisfied myself that the conditions on which the grants- in - aid was sanctioned have been duly fulfilled, are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercise:-

- Works have been supervised by Executive Engineer/ Superintending Engineer
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formalities have been observed.

3 **Physical progress achieved:-**

- Construction of Road works.
- Construction of CD works.

D.A.O
R.W.D. (W) Division.
Buxar


21.3.25
Executive Engineer
R.W.D. (W) Division.
Buxar


21.3.28

Name of Division:- RWD Works Division Buxar.

Rural Works Department
MR NEW MAINTENANCE POLICY-2018, ALLOTMENT REQUISITION

Date-20.03.2025

Name of Division:- RWD Works Division Buxar.															Date:-2024-05-20	
Sl. No.	Year	Name of Road	Name of Contractor (In English)	Project Id	Administrative Sanction		Agreement Amount (In Lacs)	Value of Hbl (in mm.km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Allotment Received (in Lacs)	Total Expenditure as per MIS (in Lacs)	Value of Measurement (in Lacs)	Current Demand (in Lacs)	Remarks	
135	2023-24	Buri - Haripur Nikris	Narendra Kumar	10401902063	3.000	160.31500	80.43429	16.95960	2082	25	5%	0.00000	0.00000	80.43429	80.43429	Physically complete

D.A.O
RWD Works Division
Buxar

21.3.25
21.3.25
Executive Engineer
RWD Works Division
Buxar

21.3.25
21.3.25

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर


का0आ0स..... बक्सर/ दिनांक.....

कार्यालय आदेश


प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत Bairi - Haripur Nikris पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत, सहायक अभियंता द्वारा 50 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।



कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा बक्सर



सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल बक्सर



कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

Name of Road:-Bairi - Haripur Nikris Contractor Name:-Narendra Kumar

Date	Time	Section	No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	ATEGORY ROAD	Latitude	Longitude	Event
20/3/25	11:03:15	61	0.1	200	10.1	2000	1880	G	25.53339	83.970449	Normal	Y = 0 * X ^ 2 + 0.816 * X + 249 X = 2125 Y = 2044
20/3/25	11:04:41	61	0.1	210	20.2	2100	1962	G	25.53365	83.96955	Normal	
20/3/25	11:05:13	61	0.1	210	20.2	2100	1962	G	25.53376	83.969114	Normal	
20/3/25	11:06:07	61	0.1	260	20.2	2600	2370	G	25.5334	83.533763	Normal	
20/3/25	11:08:01	61	0.1	210	10.1	2100	1962	G	25.53263	83.968722	Normal	(R) RURAL ROAD
20/3/25	11:09:03	61	0.1	230	10.1	2300	2125	G	25.53232	83.968722	Normal	Good
20/3/25	11:10:25	61	0.1	110	10.1	2200	2044	G	25.5337	83.968955	Normal	Average
20/3/25	11:11:01	61	0.1	210	10.1	2100	1962	G	25.53382	83.968862	Normal	Poor
20/3/25	11:12:51	61	0.1	210	10.1	2100	1962	G	25.53388	83.968037	Normal	IRI value=2082 Machine ID=19195
20/3/25	11:13:05	61	0.1	240	10.1	2400	2207	G	25.53389	83.967202	Normal	
20/3/25	11:14:08	61	0.1	230	10.1	2300	2125	G	25.53359	83.96691	Normal	
20/3/25	11:16:09	61	0.1	250	10.1	2500	2288	G	25.53316	83.966769	Normal	
20/3/25	11:16:56	61	0.1	200	10.1	2000	1880	G	25.53252	83.967078	Normal	
20/3/25	11:18:36	61	0.1	230	10.1	2300	2125	G	25.53209	83.966985	Normal	
20/3/25	11:19:09	61	0.1	110	10.1	2200	2044	G	25.5335	83.966853	Normal	
20/3/25	11:20:01	61	0.1	210	10.1	2100	1962	G	25.5337	83.966284	Normal	
20/3/25	11:21:46	61	0.1	210	10.1	2100	1962	G	25.53389	83.965861	Normal	
20/3/25	11:22:17	61	0.1	240	10.1	2400	2207	G	25.53396	83.965418	Normal	
20/3/25	11:23:05	61	0.1	230	10.1	2300	2125	G	25.5342	83.965184	Normal	
20/3/25	11:24:15	61	0.1	250	10.1	2500	2288	G	25.53427	83.964395	Normal	
20/3/25	11:25:06	61	0.1	210	20.2	2100	1962	G	25.53399	83.963895	Normal	
20/3/25	11:26:09	61	0.1	260	20.2	2600	2370	G	25.53383	83.96342	Normal	
20/3/25	11:26:46	61	0.1	210	10.1	2100	1962	G	25.53398	83.962831	Normal	
20/3/25	11:27:21	61	0.1	230	10.1	2300	2125	G	25.5339	83.962867	Normal	
20/3/25	11:27:05	61	0.1	110	10.1	2200	2044	G	25.5339	83.962867	Normal	
20/3/25	11:28:26	61	0.1	210	10.1	2100	1962	G	25.53355	83.963012	Normal	
20/3/25	11:28:51	61	0.1	210	10.1	2100	1962	G	25.53266	83.963035	Normal	
20/3/25	11:29:33	61	0.1	240	10.1	2400	2207	G	25.53186	83.96294	Normal	
20/3/25	11:31:05	61	0.1	230	10.1	2300	2125	G	25.52944	83.962718	Normal	
20/3/25	11:33:07	61	0.1	250	10.1	2500	2288	G	25.52759	83.962428	Normal	
Length				3.000								

$$Y = 0 * X^2 + 0.816 * X + 249$$

$$X = 2125$$

$$Y = 2044$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

IRI value=2082

Machine ID=19195

Kamleshwar
21.03.2025
P.S. 15.000g


21.03.25
21.07

21.03.25
AE

21.3.25
EE

File: C:\Users\VSURYANAND MISHRA\Desktop\06031354.xlsx Section No. : 61, Egn test

Name of Customer : Narendra kumar, Name of Work/ Road : bairi-haripur nikris, Lab Job number :



KMS/HR
21.03.25
243.17.1000

243.25
243.25

21.03.25
AE

21.03.25
EE