

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Mowing of grass - Belah Lachhi - 1000 sqm					
② Agency - 500 sqm construction of 1st floor					
③ Agreement - 1000 sqm - 50/18-19					
④ Actual reading of completion - 14-06-2020					
⑤ Restoration of 200 sqm					
	380	2.4	0.85	0.70	54.26 m ²
	56	1.95	0.80	0.75	65.52 m ²
	50	2.6	0.80	0.65	67.6 m ²
					187.38 m ²
⑥ Maintenance of Earthwork					
	43	30	0.80	--	1032.0 m ²
	1	13.5	0.25	--	11.457 m ²
					1043.457 m ²
				22	1043.44 m ²
⑦ Patch holes Repair					
	5.9	1.85	--	--	10.91 m ²
	13.4	2.25	--	--	30.15 m ²
	11.95	2.85	--	--	34.05 m ²
⑧	19	2.65	--	--	50.35 m ²
⑨	15	2.40	--	--	36.0 m ²
⑩					161.46 m ²
⑪ Patch repair					
	Area under 1st floor				161.46 m ²
⑫					

⑬ Number of 1000 sqm - 6.0 m

Continuation

10/06/2023
JE

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
6. Maintenance flat type culvert					
	T.M.B. P(34) -			1-0	
	Q.B. 2251 = 84/each				2252
7. Maintenance road signs					
	T.M.B. P(94) -			2.65 kg	
	Q.B. 1648 = 57/1 kg				2777
8. Maintenance 200mtr km per					
	T.M.B. P(94) -			2.65 kg	
	Q.B. 696 = 18/1 kg				1845
	(only 1061203 SE)				205988