rtified that this measurement

1st year Maintenance Bill

Sch. XLV-Form No. 134

Particulars	Details of actual measurement No.	L.	B.	D.	Contents of area
Name of work :- Dakbangla Sq to Chaudhari Hote Hue Harni tola Tak in MMGSY scheme (Gen) in Auraiya Block.					
Agency :- Suresh Ray					
Agreement No - MMGSY/SBD-56/19-20					
Date of workorder :- 21-12-19					
Measurment					
1) Restoration of rain cuts with Soil etc.					
9 x 8.50 x 1.25 x 0.30 =>					6.37m³
3 x 8.00 x 1.58 x 0.30 =>					11.37m³
4 x 6.95 x 1.68 x 0.30 =>					14.01m³
3 x 9.55 x 1.46 x 0.30 =>					12.54m³
					44.29 m³
2) Making up loss of materials irregularities on shoulders etc.					
2 x 3 x 30 x 1.14				=>	205.2m²
2 x 2 x 9 x 1.14				=>	41.04m²
					246.54 m²

Continuation

Sch. XLV-Form No. 134

BF ⇒ 47725.38

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
6) Maintenance of culverts					
vide Page No			—	(51)	
4No @		2309	03	⇒	9236=00
				Rs ⇒	50961.38
Less 10% Below					5096.13
				Rs ⇒	45865.25
			Say	Rs =	45865=00
		Shain 25/10/24 AE			
Soil - 44.29 m3					
Stone chips → 0.55 m3					