

| Particulars                                            | Details of actual measurement |    |    |    | Contents of area |
|--------------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                        | No.                           | L. | B. | D. |                  |
| 7th year Maintenance                                   |                               |    |    |    |                  |
| Name of Road $\rightarrow$ L036 (Gadoli) to Devgon Tal |                               |    |    |    |                  |
| Agency $\rightarrow$ Mamoj Kumar Ray                   |                               |    |    |    |                  |
| Agg No $\rightarrow$ MMGSY/SBD-85/2021-22              |                               |    |    |    |                  |
| Agg value $\rightarrow$ 6536146.00                     |                               |    |    |    |                  |
| Rate 2.31% Below                                       |                               |    |    |    |                  |
| Date of work order - 23/11/2021                        |                               |    |    |    |                  |
| Date of completion - 22/8/2022                         |                               |    |    |    |                  |
| Local art                                              |                               |    |    |    |                  |
| 2nd year maintenance of road                           |                               |    |    |    |                  |
| 6536146.00                                             |                               |    |    |    |                  |

| Measurement                                |   |  |  |                      |
|--------------------------------------------|---|--|--|----------------------|
| 1) Restoration of rain cuts with soil e.c. |   |  |  |                      |
| 3 x 8.61 x 1.48 x 0.30                     | = |  |  | 11.46 m <sup>3</sup> |
| 2 x 6.55 x 1.28 x 0.30                     | = |  |  | 5.03 m <sup>3</sup>  |
| 2 x 5.00 x 1.25 x 0.30                     | = |  |  | 3.75 m <sup>3</sup>  |
|                                            |   |  |  | 20.24 m <sup>3</sup> |
| 2) Maintenance of Earthen Shoulder.        |   |  |  |                      |
| 2 x 30 x 1.15                              | = |  |  | 69 m <sup>2</sup>    |
| 2 x 20 x 1.15                              | = |  |  | 46 m <sup>2</sup>    |
|                                            |   |  |  | 115 m <sup>2</sup>   |

