

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>2nd year Maintenance</u>					
Name of Road $\rightarrow$ 1036 (Gatali) to					
Devgon Tak					
Agency $\rightarrow$ Mamraj Kumar Ray.					
Agg No - MMHSY/SBD-85/2021-22					
Agg value $\rightarrow$ 6536146 = 00					
Rate 2.31 % Below					
Date of work order - 23/11/2021					
Date of completion - 22/8/2022					

<u>Measurement</u>					
1. Restoration of Rain cuts					
with soil etc.					
$3 \times 5.55 \times 1.48 \times 0.30 = 7.39 \text{ m}^3$					
$4 \times 7.25 \times 1.48 \times 0.30 = 12.87 \text{ m}^3$					
$2 \times 6.00 \times 1.28 \times 0.30 = 4.60 \text{ m}^3$					
$7 \times 3.55 \times 1.51 = 24.86 \text{ m}^3$					
2. Maintenance of Earthen					
Shoulder etc.					
$2 \times 30 \times 1.15 = 69 \text{ m}^2$					
$2 \times 20 \times 1.15 = 46 \text{ m}^2$					
$2 \times 10 \times 1.16 = 23.2 \text{ m}^2$					
<u>138.2 m²</u>					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

[illegible]