

4th Year Maintenance

37

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - const/maint of road					
from Sakaldeo Rai ke ghar					
to Amayay Pakki Tak					
Agency -	Nirmala Devi				
Agreement No -	03/SBD/2019-2020				
Date of work order -	13-06-2019				
Date of Actual Completion	30-12-2020				
	S.M.D. Moha Division 200604				
	S.M.D. Moha Division 200604				

Record Measurement

Item No (1)	Plaster restoration				
	of cement with soil				
	moorum -				
	2	3.75	0.80	0.30	$= 1.80 m^3$
	3	2.25	0.85	0.30	$= 1.72 m^3$
	2	4.30	0.90	0.30	$= 2.32 m^3$
	4	4.10	0.90	0.30	$= 4.43 m^3$
	5	6.25	0.95	0.30	$= 8.91 m^3$
	3	5.75	0.95	0.30	$= 4.92 m^3$
	1	9.50	1.00	0.30	$= 2.85 m^3$
	3	5.50	0.85	0.30	$= 4.21 m^3$
	4	3.25	0.85	0.30	$= 3.31 m^3$

Continuation

Continuation