

519 year maintenance

50

Sch. XLV--Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: -					Nilafur SI No
					Ordnance to Panchayat
					Drawn hole name
					Kumari nursery Pali.
Agency :-					M/s. Galvin. Conf.
Actual completion					14/10/19
					Record Entry
1 Restoration of mounds -					
					1 x 52.0 x 0.90 x 0.30 = 14.04 m ³
					2 x 41.50 x 0.75 x 0.30 = 18.67 m ³
					1 x 35.00 x 0.85 x 0.30 = 8.92 m ³
					1 x 45.00 x 0.90 x 0.30 = 12.15 m ³
					2 x 41.10 x 0.85 x 0.30 = 15.86 m ³
					1 x 48.00 x 0.90 x 0.30 = 12.96 m ³
					1 x 45.0 x 0.75 x 0.30 = 10.12 m ³
					2 x 39.0 x 0.85 x 0.30 = 19.89 m ³
					112.61 m ³
2. Making up loss of material -					
					1 x 52.00 x 0.90 (w) = 46.80 m ²
					2 x 45.00 x 0.85 (w) = 76.50 m ²
					1 x 65.00 x 0.90 (w) = 58.50 m ²
					2 x 39.10 x 0.85 (w) = 99.70 m ²
					1 x 58.00 x 0.85 (w) = 44.20 m ²
					4 x 35.50 x 0.80 (w) = 113.60 m ²
					2 x 38.0 x 0.90 (w) = 68.40 m ²
					1 x 82.0 x 0.80 (w) = 65.60 m ²
					2 x 39.50 x 0.85 (w) = 51.85 m ²
					625.15 m ²

Continuation

BRS. 98377.10

54

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					RS - 98377.10
					less than 10% below C) 9837.70
					RS 88539.30
					SAY - 88539.10

~~Agenda~~
10/11/25
7E

~~Agenda~~
10/11/25
AC

CSP
10/11/25
25

Material Statement

(i) Soil - 112.61 m³

(ii) Bitumen - 0.021 m³

(iii) Emulsion - 0.020 m³

(iv) Stone chip - 0.875 m³

~~Agenda~~
10/11/25
7E