Sch. XLV-Form No.134 17

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	5th year Maintenance.				
N/w:→	Mainth. of road from Garahia				
	Mushar tola to MMGSY				
	Madhubar Garahia Path under				
	GTSNY.				
Agency:→	Rajeev Kumar				
	New chandmari, Motihari				
	East champaran.				
Agreement no:→	02 SBD/2019-20				
Actual Date of completion →	09.11.2019				
D.O.M →	09.11.2024				

1.) Restoration of raincuts					
—do— all comp. job.					
2x	5x	30x	1.25x	0.300 =	112.50 M³
2x	1x	12x	1.25x	0.300 =	9.00 "
					121.50 M³
2.) Maintenance of Earthen					
Shoulder —do— all comp. job.					
	2x	5x	30x	1.25 =	375.00 M²
	2x	4x	30x	1.25 =	300.00 "
					675.00 M²
3.) Maintenance of culverts					
—do— all comp. job →					1.00 NOS.

09/11/24
J.E

Continuation

Scanned with CamScanner

Sch. XLV-Form No.134 18

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT OF COST				
1.) Restoration of raincuts					
—do— all comp. job.					
121.50 m^3	vide	T4B	P-17		
@Rs. 359.74/m^3				Rs.	43,708=00
2.) Maint. of Earthen					
Shoulder —do— all comp.					
job.					
675.00 m^2	vide	T4B	P-17		
@Rs. 53.91/m^2				Rs.	36,389=00
3.) Maintenance of culverts					
—do— all comp. job.					
1.00 no.	vide	T4B	P-17		
@Rs. 1104.35 each				Rs.	1104=00
				Rs.	81,201=00
less 0.15% below				(-) Rs.	122=00
				Rs.	81,079=00

09/11/24
J.E

Continuation

Scanned with CamScanner