

(Mmgsy) Natesha to Rajabitha via Rajendra
(SC) Schedule XLV-Form No. 134 Mayas-

~~Qalln~~

Mmgsy (SC)

DIVISION

Miss Raj Lakshmi Const & Obs DIVISION

PT0068404

Measurement Book

Vol-II

1091

2nd year maintenance Bill

20

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
M/w - maintenance of Road from					
Nateshar to Raja bigha via					
Rajendra Nagar					
Agency - M/S Rajlaxmi Const.					
Agrent No - 11 SBD/2020-21					

Receipt Entry				
① Restoration of Rain cut - - Comp - -				
5	30.00	1.25	0.30	= 56.25 m ³
3	30.00	1.25	0.30	= 33.75 m ³
2	10.00	1.25	0.30	= 7.00 m ³
				97.5 m ³
② Making up of berms & shoulder - - Comp - -				
2	3	30.00	1.25	= 225.00 m ²
2	3	30.00	1.25	= 225.00 m ²
2	2	18.00	1.25	= 90.00 m ²
				540.00 m ²

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(15) white washing on parapet wall --- --- Comp ---					
Area	2x	21.00		=	42.00 m ²
After					
8/5/25					
S.E					

ABSTRACT of cost

(1) Restoration of Raincoat
--- Comp ---

Qty ride TMBP-(20) = 97.50 m³

① RS 386.14 / m³ : RS 37649.00

(2) making up of berms
& shoulder --- Comp ---

Qty ride TMBP-(20) = 540.00 m²

① RS 57.36 / m² : RS 30974.00

(3) Repair of Pot hole
--- Comp ---

Continuation

Co-68623.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Qty vide TM BP - (21) =				0.23 m ³	
④ RS 9079.35 / m ³				= RS	2088.00
④ Patch repair over pot hole -- Comp --					
Qty vide TM BP - (21) =				75.14 m ²	
④ RS 235.95 / m ²				= RS	17729.00
⑤ Patch repair over Bitumen surface -- Comp --					
Qty vide TM BP - (21) =				75.14 m ²	
④ RS 253.06 / m ²				= RS	19015.00
⑥ Filling of crack & joint -- Comp --					
Qty vide TM BP - (22) =				1605.00 m	
④ RS 3.96 / m				= RS	6356.00
⑦ Repair of concrete pavement -- Comp --					
Qty vide TM BP - (22) =				9.21 m ²	9.21 m ³
④ RS 235.95 / m ²				= RS	2173.00
⑧ Repair of old joint sealant -- Comp --					
Qty vide TM BP - (22) =				182.50 m	
④ RS 23.48 / m				= RS	4403.00

Continuation CO = 120387.00

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				Bf =	120357.0
⑨ maintenance of H.P					
Culvert - - Comp					
Qty vide TMBP-(23) = 2 No.					
@ RS 1130.67/each				= RS	2261.0
⑩ mainten of Road					
Sign - - Comp					
Qty vide TMBP-(23) = 1.81 km					
@ RS 1077.81/km				= RS	1951.0
⑪ maintenance of 200m					
8 Km Stone - - Comp					
Qty vide TMBP-(23) = 1.81 km					
@ RS 628.22/km				= RS	1137.0
⑫ cutting of branch of					
trees & shrubs - -					
Qty vide TMBP-(23) = 11 No.					
@ RS 109.74/each				= RS	1207.0
⑬ cutting of shrubs					
from road way - - Comp					
Qty vide TMBP(23) = 1605 No					
@ RS 6.73/each				= RS	10802.0
⑭ Pruning of grass &					

Continuation Co = 137745.0

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				BF =	137745.0
woods - camp					
Qty ride TMS - (63) =					3605 m ²
@ RS 2.24 / m ²				RS	8075.0
(15) white washing on					
parapet wall - camp					
Qty ride TMS - (24) =					42.0 m ²
@ RS 16.24 / m ²				RS	681.0
					146501.0
WST @ 12% (f)					17580.0
Le cess @ 1%					1465.0
					165346.0

less below @ 0.04% (-) 66.80
165480.0

~~Atten~~
8/5/25
JE

~~Atten~~
08.05.2025
DL

Continuation