

MIMGSY (SC) 145BC

020-21

MIMGSY SC

Shedule XLV Form No. 134.

Bayasi

DIVISION

Amour

SUB-DIVISION

Measurement Book

No. 1110

Halya

3rd Year Abstract of cost

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Ruins (item 1 p. 59)					
80.25 M ³ @ RS = 380.58/M ³ = 30542 = ∞					
② Making up of Berms/Shoulder (item 2 p. 59)					
446.25 M ² @ RS = 58.37/M ² = 26048 = ∞					
③ Repair of potholes 25mm w.B. (item 3 p. 60)					
69.80 M ² @ RS = 357.05/M ² = 24922 = ∞					
④ Bituminous Surface 20mm m.S (item 4 p. 60)					
69.80 M ² @ RS = 247.59/M ² = 17282 = ∞					
⑤ Maint. of H.P Culvert (item 5 p. 60)					
1.00 NOS @ RS = 1117.00/piece = 1117 = ∞					
⑥ Maint. of Road Sign (item 6 p. 60)					
0.21 KM @ RS = 1074.51/KM = 227 = ∞					
⑦ Maint. of 200mm & KM Stone (item 7 p. 60)					
0.25 KM @ RS = 573.96/KM = 146 = ∞					
⑧ Cutting of branches of tree (item 8 p. 60)					
2.00 NOS @ RS = 106.52/piece = 213 = ∞					
⑨ Cutting of Shrubs from Roadway (item 9 p. 60)					
10.00 NOS @ RS = 6.54/piece = 65 = ∞					

Rs. 100562 = ∞

Continuation

[illegible]