

with Hoese of Lakar Station to (MM 84950  
manila)

# Schedule XLV-Form No. 134

Engineer  
(V) Division  
Mott

DIVISION

A. E. L. D. (20) SUB-DIVISION  
just arriving.

MB. 40.6483.

MEASUREMENT BOOK

Alok Kumar

## Sch.XLV-Form No. 134

| Particulars                                                                                   | Details of actual measure |      |      |      | Contents of area    |
|-----------------------------------------------------------------------------------------------|---------------------------|------|------|------|---------------------|
|                                                                                               | No.                       | L.   | B.   | D.   |                     |
| Name of Work - Maintenance of Road from H/o Laban Sahani to H/o Raghav Patel under (mains) SC |                           |      |      |      |                     |
| Agency:- Abhis Kumar.                                                                         |                           |      |      |      |                     |
| Agreement no - 42528307-2020-21                                                               |                           |      |      |      |                     |
| Date of Start - 22.07.2020                                                                    |                           |      |      |      |                     |
| Actual Date of comp - 23.03.21                                                                |                           |      |      |      |                     |
| Date of comp - 21.07.2021                                                                     |                           |      |      |      |                     |
| 3rd Year Maintenance Period                                                                   |                           |      |      |      |                     |
| = 24.03.2021 to 23-03-25                                                                      |                           |      |      |      |                     |
| 1                                                                                             | Restoration of            |      |      |      |                     |
| 15"                                                                                           | rain cut                  |      |      |      |                     |
|                                                                                               | Berms with                |      |      |      |                     |
|                                                                                               | Soil - do -               |      |      |      |                     |
|                                                                                               | 5                         | 4.50 | 0.35 | 0.30 | 6.413m <sup>3</sup> |
|                                                                                               | 8                         | 7.50 | 0.85 | 0.25 | 12.75 "             |
|                                                                                               | 5                         | 5.00 | 0.85 | 0.30 | 5.25 "              |
|                                                                                               | 10                        | 8.50 | 0.70 | 0.30 | 22.95 "             |
|                                                                                               | 15                        | 9.00 | 0.90 | 0.25 | 25.31 "             |
|                                                                                               | 12                        | 4.50 | 0.75 | 0.30 | 14.58 "             |
|                                                                                               | Total =                   |      |      |      | 87.25m <sup>3</sup> |

Continuation

Continuation