

4th years maintenance

42

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents ³ of area
	No.	L.	B.	D.	
1. Name of work: Halka to megha koigari					
2. Name of agency: Nandkhor N					
				THAKUR	
3. Agreement No: 12/SAD/2020-21					
4. Actual dt. of completion: 27.05.2021					
Work done					
① Restoration of green cuts with soil - dw. E.R.					
	1	20.50	1.00	0.30	6.15
	1	20.60	0.80	0.30	19.776
	3	20.80	0.75	0.28	13.102
	2	10.50	0.72	0.32	4.838
	2	20.60	0.70	0.30	8.652
	1	2.50	0.72	0.30	0.54
					Qty = 53.06 m ³
					Say Qty = 52.81 m ³
② 1/2 maintenance of earthen shoulder - dw. E.R.					
	4	20.60	0.90		74.16
	3	20.85	0.80		50.04
	4	20.80	0.72		59.904
	4	20.75	0.73		60.59
	2	24.34	1.0		48.68
					Qty = 293.374 m ²
					Say Qty = 293.40 m ²
③ 3/3 Repair to pot holes on ip					


Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					B P B 97286=00
Add 1% Labour					973=00
Add 12% C.S.P.					11574=00
					B 109933=00
Less 10.0% below					10993=00
					B 98940=00


 28.04.2015
 J.R.

material Statement

- (i) earth — 96.82 m³
 (ii) Bitumen 5% — 271.42 kg
 (iii) Stone chips — 3.67 m³


 28.04.2015
 J.R.