

Shiv mandir Daudnagar Chowk (Hazipur-Maharaj

Schedule XLV-Form No. 134

Path) Se South Branga Ghat

M. M. G. S. Y
(SC)

Maharaj

DIVISION

Bidupur

SUB-DIVISION

MEASUREMENT BOOK

760

2nd year unit 134

Sch

Sch. XLV—Form No. 134

45

Pa

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work					Shivmandir
2. Location					Naundgaon Chowk
3. (Kasipur Mahan fort)					
4. Se South gunga ghul					
5. Agency - life vision Const. Pvt. Ltd.					
6. Ag. No. - 89/111764/20-21					
Date of work order					
					7.01.2021
Date of completion					
					5/1/22
					Received Survey

1. Restored all main cuts					
----- in					
all Cuts					
2x4 x 21 x $\frac{0.90+1.10}{2} \times 0.20m = 33.60m^3$					
2x3 x 14 x $\frac{0.70+0.90}{2} \times 0.20m = 20.16m^3$					
1x7 x 19 x $\frac{1.00+0.80}{2} \times 0.20m = 23.94m^3$					
2x9 x 14 x $\frac{0.70+0.90}{2} \times 0.20m = 40.32m^3$					
					= 118.02m ³
					116.94m ³
2. pks. Bury cut after					
main Cuts					
----- in all					
Cuts					
2x55 x 30 x 0.10 = 330.00m ³					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of Cost					
1) Restoration of main					
Cuts — — — in					
all concrete					
Qty. vide run up (48)					
$\approx 116.94 \text{ m}^3 @ 419.31/-$					≈ 49034.00
2) pile laying bed approx					
concrete					
— — — in all					
Qty. vide run up (48)					
$\approx 330.00 \text{ m}^3 @ 721.95/-$					≈ 238244.00
3) repair of road sign					
— — — in all					
concrete					
Qty. vide run up (46)					
$\approx 0.25 \text{ m}^3 @ 1145.81/-$					≈ 286.00
4) main of road sign					
Qty. — — — in all					
concrete					
Qty. vide run up (46)					
$\approx 0.30 \text{ m}^3 @ 654.66/-$					≈ 196.00
					≈ 287760.00
As per Agd G.S. (19.1) (4)					≈ 37409.00
					≈ 325169.00
As per Agd below (13.55%) (1 C)					≈ 44060.00
					≈ 281109.00

Continuation

11/2/15
 A.P.

11/2/15
 J.E.