

Name of work: - Const. of Road from
 5012 to Gungawn Pachu Brghe
 Cent. - Cuddikumar
 Agreement no: - 48/SBD/2019-20
 Act. date of completion: - 27-11-2020
 Sch. XLV-Form No. 134
 Date of measurement: - 24-11-2021

Date of Measurement		Details of actual measurement				Contents of area
Particulars		No.	L.	B.	D.	
1st Year Maintenance						
1. Restoration of rain cut with soil						
			17	1.00	0.90	0.30 = 4.59 m ³
			21	3.00	1.00	0.30 = 18.90 m ³
			7	2.00	0.95	0.30 = 3.99 m ³
			27	3.20	0.90	0.30 = 23.33
			20	1.90	1.10	0.30 = 12.54 m ³
						63.35 m ³
2. Making up berms/shoulder						
			17	4.00	1.00	= 68.00 m ²
						= 36.30 m ²
			10	2.00	0.90	= 18.00 m ²
			21	5.00	1.05	= 110.25 m ²
			33	4.00	0.90	= 118.80 m ²
						351.35 m ²
3 Patch repair over bitu-minous surface.						
			20	0.90	0.60	= 10.80 m ²
			17	1.20	0.90	= 18.36 m ²
						29.16 m ²
4. Maintenance of Turne pipe culvert						
			14	2.22	1.00	
5. Maintenance of road signs.						
			4	30.00	1.20	0.00 m
			1	10.20	1.00	0.00 m
			20	130 km	130.00 m	

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
6. Maintenance of 250m and Km. Stone					
	54	30.00			150.00 m.
					= 0.150 km.
7. Cutting of branches of trees & shrubs					
	143				3 nos
8. Cutting of shrubs from road way.					
	14	1251			1251 nos
9. Trimming of grass & weeds.					
	17	30.00			510.00 m ²
10. White washing of parapet of C.D.					
	4	6.00	0.60		14.40 m ²
	4	6.00	0.40		9.60 m ²
	4	6.00	0.65		15.60 m ²
	8	0.40	0.60		1.92 m ²
					41.52 m ²
	Agg 24/11/21				
	S.E.				

Particulars	Details of actual measurement				Content of area
	No.	L.	B.	D.	
Material Statement					
1. Soil					$100.215 m^3$
2. Stone Aggregate					$0.79 m^3$
3. Coarse Sand					$0.175 m^3$
4. Emulsion					$0.0093 M-T$
5. Bitumen					$0.0554 M-T$
AM					
24/11/21					
SE					

Abstract of cost.					
1/1 Restoration of rain cuts with soil	sty. value TMB item.				
	MD 1 PM 28 = $63.35 m^3$				
	@ $1380 = 58/m^3$ — MD 24110 =				
2/2 Making v/bes m/s shoulder	sty. value TMB item.				
	MD 2 PM 28 = $35.35 m^3$				
	@ $158 = 37/m^2$ — MD 20508 =				
3/5 Patch repair over bituminous surface	sty. value TMB item				
	MD 3 PM 28 = $29.16 m^2$				

Continuation

@ $292 = 67/m^2$ — MD 534 =
 @ $10 = 53,152 =$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					B/F — 1553, 1525
4/11 Maintenance of Turnpike culverts.					
Qty. side TMB item					
NO 4 PM 28 = 2 nos.					
CM 11720 each — B 2234 =					
5/14 Maintenance of road signs.					
Qty. side TMB item					
NO 5 PM 28 = 0.130 km					
CM 1074 = 51/km — B 140 =					
6/15 Maintenance of road					
Qty. side TMB item					
NO 6 PM 29 = 0.150 km					
CM 657 = 71/km — B 992 =					
7/16 cutting of branches of trees & shrubs.					
Qty. side TMB item					
NO 7 PM 29 = 3 nos.					
CM 106 = 52 each — B 320 =					
8/17 cutting of shrubs from roadway.					
Qty. side TMB item					
NO 8 PM 29 = 125/NO.					
CM 6 = 54 each — B 8182 =					
C/O — NO 64, 127 =					

Continuation

[illegible]