

M.M.G.S.Y - Logo to Bhadwar (Lachhanath) - 1.519 km

Schedule XLV-Form No. 134

Ag.No- 52 S.B.D- 2020-2021

Sherghati DIVISION

Sherghati SUB-DIVISION

Gantosh Kumar Gupta

Measurement Book

1220

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4th year maintenance					
Bill -					
N/W - maintenance of road from					
1029 to Bhadrwar Lachnaiti					
Agency - Santosh Kumar Gupta					
Karmauni Bhavi 201 Gaya					
Agreement No - 52/SBD/2020-21					
Date of W/O - 30-06-2020					
Date of Comp. 29.06.2021					
Actual Date of Com - 25.06.2021					
①	Reclamation at Rm 7 cady				
	Berm with soil do-do				
	5	16.00	0.95	0.30	$= 22.83m^3$
	22	5.00	0.90	0.30	$= 24.75m^3$
	18	4.00	0.85	0.30	$= 18.36m^3$
	4	10.0	1.00	0.30	$= 12.00m^3$
	15	6.00	1.00	0.30	$= 27.00m^3$
					$= 104.91m^3$
			Limit		$= 100.36m^3$
②	making up 4-Berms/				
	shoulder do-do -				
	30	4.00	0.90		$= 108m^2$
	25	9.00	0.85		$= 191.25m^2$
	18	8.00	0.90		$= 129.60m^2$
	17	8.00	0.80		$= 122.40m^2$
					$551.25m^2$

10/05/25
JE

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B.P. Rs =	70526=00
(3)	Repair of pot-holes filled with 15 mm do - do -				
	Quant. vide TMBP No. 61				
	Item No - 03				
	0.340 m ² @ 932.91/m ² Rs =				3169=00
(4)	Patch repair over bitu pot-holes with 20 mm do -				
	Quant. vide TMBP No. 61				
	Item No - 04				
	115.0 m ² @ 240.54/m ² Rs =				27,662=00
(5)	Patch repair over bitu surface with 20 mm do -				
	Quant. vide TMBP No. 61				
	Item No - 05				
	115.0 m ² @ 257.66/m ² Rs =				29,630=00
(6)	Crack sealing filling of crack and joint do - do -				
	Quant. vide TMBP No. 61				
	Item No - 06				
	1244 m @ 3.96/m Rs =				4926=00
(7)	Repair of concrete pavement - do - do -				
	Quant. vide TMBP No. 61				
	Item No - 07				
	25.24 m ² @ 240.54/m ² Rs =				6071=00
				Total Rs =	141984=00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	B.	
			B.P	Rd =	141984.00
(8) Repair of old Joint sealant					
Removal etc - - do - -					
Quant. vide TMB P No-62					
item No - 08					
257.82m @ 23.48/m Rd =					6053.00
(9) maintenance of C/D					
work do - - do - -					
Quant. vide TMB P No-62					
item No - 09					
02 No @ 1130.67/No Rd =					2261.00
(10) maintenance of C/D					
work do - - do - -					
Quant. vide TMB P No-62					
01 No @ 2329.21/No Rd =					2329.00
(11) maintenance of Road					
sign do - - do - -					
item No - (11)					
Quant. vide TMB P No-62					
1.52 km @ 1073.81/km Rd =					1638.00
(12) maintenance of 200m					
and km stores do - do -					
Quant. vide TMB P No-62					
item No (12)					
1.52 km @ 628.22/km Rd =					954.00
				Total Rd =	15529.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B.F.	Rd =	155219.00
(13) Cutting of branches of trees and shrubs do. do.					
Quant. vide MB P.No. 62					
Item No. 13					
09 No @ 109.74/No Rd =					987.00
(14) Cutting of shrubs from roadway do. do.					
Quant. vide MB P.No. 62					
Item No. 14					
1244 No @ 6.73/No Rd =					8372.00
(15) Trimming of grass and weeds					
Quant. vide MB P.No. 62					
Item No. 15					
2775.00 m ² @ 2.24/m ² Rd =					6216.00
(16) White washing of parapet walls of C/D works do. do.					
Quant. vide MB P.No. 63					
Item No. 16					
61.2 m ² @ 16.91/m ² Rd =					992.00
				Total Rd =	171786.00
Sum 10575 JE					