

4th year Maintenance

Sch. XLV-Form No.134 20

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W: - Maintenance of Road from					
Bokaro-Jaithubari Road to Mayhau					
- by Jaithubari to Paschim to					
M. G. S. 'SC'					
Block - Pakaridgaal					
Agency: - M/s. Maa Durga Construction					
& Supplier.					
Semra, Chakia					
E. Chamba					
Agreement No: - E6 SBP/2018-19					
Actual Date of comp: - 31.8.2020					

Main Work has been					
done by Agency					
1. Restoration of Main					
cut with soil etc.					
2x	6x	9.60x	0.80x	0.30	27.64
2x	8x	8.20x	0.70x	0.30	27.55
2x	10x	6.80x	0.60x	0.30	24.48
2x	12x	5.30x	0.50x	0.30	19.08
2x	14x	4.00x	0.40x	0.30	13.44
2x	16x	2.71x	0.45x	0.30	11.70
T					123.89 m ³
2. Maintenance of Road					
Shoulder filling etc.					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2x 4x	12.80	x	0.85		= 87.04 ✓
2x 6x	10.60	x	0.75		= 95.40 ✓
2x 8x	8.40	x	0.65		= 87.36 ✓
2x 10x	6.20	x	0.55		= 68.20 ✓
2x 12x	4.80	x	0.60		= 57.60 ✓
2x 14x	2.10	x	0.70		= 41.16 ✓
				T	419.48m
			Limit	—	418.90m
3. Maintenance of WBV Road					
including filling potholes —					
3x 4.10	x	2.80			= 34.44 ✓
10x 1.80	x	1.10			= 19.80 ✓
16x 0.80	x	0.60			= 7.68 ✓
10x 8.34	x	0.30			= 25.02 ✓
				T	86.94m ²
4. Repair to Potholes					
by removal —					
3x 4.10	x	2.80			= 34.44 ✓
10x 1.80	x	1.10			= 19.80 ✓
16x 0.80	x	0.60			= 7.68 ✓
10x 8.34	x	0.30			= 25.02 ✓
				T	86.94m ²
5. Patch repairs manually					
filled —					
3x 4.10	x	2.80			= 34.44 ✓
10x 1.80	x	1.10			= 19.80 ✓
16x 0.80	x	0.60			= 7.68 ✓

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	10 x	8.34	0.30		25.02
				T	86.94 m ²
6. Mainline H.P. culverts					
by 8-way				4.	2 No
7. Cutting & branches of					
tree				4.	10 No
8. Cutting & shrubs from					
1-way				4.	20.01 No
9. Trimming of ground					
weeds from 1-way					
2 x 27 x 30.00 x 0.50					810.00
				T	810.00 m ²
				Limit	774.49 m ²
10. White Washing of					
wall				20.	
Top.	4 x	6.150	0.40		9.84
End.	8 x	0.40	0.60		1.92
S. L.	4 x	6.150	0.60		14.76
				T	26.52 m ²
11. Mainline of 200y d.k.m					
stone by way					0.288 km
12. Mainline of 400y d.k.m					
by way					4.200 km
2.9.94.					
J.E.					

Continuation

Abstract of cost.

Sch. XLV-Form No.134 23

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1/1 Restoration of Rain cuts with soil		P-20			
123.89 m ² ① &		365.25		6.	45251 ✓
2/2 Maintenance of Bankers shoulder filling		P-21			
418.90 m ² ① &		54.237		6.	22776 ✓
3/4 Mainls & W.B. road incl. incl. filling		P-21			
86.94 m ² ① &		384.03		6.	33388 ✓
4/3 Repair to Pot hole by removal		P-21			
86.94 m ² ① &		287.70		6.	25013 ✓
5/5 Patch repair on already filled		P-22			
86.94 m ² ① &		271.94		6.	23642 ✓
6/7 Mainls & H.P. curbs by way		P-22			
2 NO ① &		1131.64		6.	2263 ✓
7/12 Cutting of branches of tree by way					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		P-22			
10 No (D) L.		107.48		L.	1075.0 ✓
8/13	Cutting of Shrub as from				
	R. way				
		P-22			
20.01 No (D) L.		6260		L.	132 ✓
9/14	Trimming of grass and				
	weeds from J. way				
		P-22			
774.49 m ² (D) L.		2220		L.	1704 ✓
10/15	White washing of fence				
	pub wall				
		P-22			
26.52 m ² (D) L.		16280		L.	446 ✓
11/11	Maintenance of 2004 L. key				
	store				
		P-22			
0.288 key (D) L.		74920		L.	216 ✓
12/9	Maintenance of road sign				
	by way				
		P-22			
4200 key (D) L.		1087263		L.	4568 ✓
				L.	160979.00 ✓
less 0.05% below on L.					80.00 ✓
				L.	160394.00 ✓
By 2.9.94. J.E.					
	Painted				
	02/09/24				
	AV				

Continuation