

3rd Year Maint

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
W/m - Maint. of road from 2073 to Vicalpur.					
Agency - M/S Raja Construction					
Ap. No - 41/2021-2022					
Date of start - 01/04/2021					
Actual completion - 30/04/2022					

Record Entry

① Restoration of rain
cut - 00 -

$$4 \times 6.60 \times 0.90 \times 0.80 = 7.12$$

$$4 \times 6.80 \times 0.95 \times 0.80 = 7.75$$

$$14.88 \text{ m}^3$$

② Maint. of Southern
Shoulder - 00 -

$$2 \times 9 \times 6.60 \times 0.95 = 112.86$$

$$2 \times 8 \times 5.80 \times 1.10 = 102.08$$

$$2 \times 6 \times 6.80 \times 1.05 = 79.38$$

$$2 \times 4 \times 4.20 \times 0.85 = 28.56$$

$$322.88 \text{ m}^3$$

③ Repair of potholes
filled with 75 mm - 00 -

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
① Restoration of rain cuts — 00 —					
14.88 m ² — wide — P-61					
404.06/m ² — — — 6					6014.0
② Maint. of earthen shoulder — 00 —					
892.88 m ² — wide — P-61					
@ 60.48/m ² — — — 8					19527.0
③ Repair of pat holes — 00 —					
14.75 m ² — wide — P-62					
@ 421.80/m ² — — — 5					6222.0
④ Patch repair over pat holes — 00 —					
14.75 m ² — wide — P-62					
@ 267.64/m ² — — — 5					3948.0
⑤ Maint. of stone pipe culvert — 00 —					
01 Nos. — wide — P-62					
@ 1166.58/each — — — 6					1167.0
⑥ Maint. of road sign — 00 —					

Continuation

Continuation