

44 years maintenance

57

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: pokhara					
Darsin Tola Pmssy Sarak					
Rampavesh Bhagat ke char					
Se Jagdish Ray ke pul Hote					
Huye to Lalgarh Pokhara					
pitch road Tak					
2. Name of Agency: Suresh Kumar					
3. Agreement No: 104/SAD/2019-20					
4. Actual dt. of completion: 08.03.2021					
— Work done —					
① Restoration of main cut					
with 40% - 40%					
1x 20.50 x 0.50 x 0.30 = 3.075					
2x 20.80 x 0.50 x 0.30 = 6.24					
2x 11.80 x 0.48 x 0.32 = 5.437					
8x 20.85 x 0.48 x 0.28 = 22.460					
7x 30.0 x 0.48 x 0.30 = 30.24					
8x 20.95 x 0.52 x 0.32 = 27.888					
1x 23.50 x 0.48 x 0.30 = 3.384					
					Qty = 98.724m ³
					Say Qty = 97.520m ³
② 1/2 maintenance of borders					
shoulder - 40% 1/2					
5x 20.90 x 0.50 = 52.25					
8x 30.0 x 0.50 = 120.0					
10x 30.0 x 0.50 = 150.0					
10x 30.0 x 0.48 = 144.0					
2x 30.0 x 0.45 = 27.0					
6x 20.00 x 0.40 = 48.00					
1x 3.50 x 0.50 x 0.30 = 0.525					
Continuation					
C.O. Qty = 541.775m ³					

Scanned with CamScanner