

3rd year maintenance

22

Sch. XLV—Form No. 134

Sch. XLV—Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
N/w:- Maintenance of Road from Fatain Chak to Mali tola.					
Ageny:- Shri Shakti Construction					
Agot No:-					
Date of Start:-	17/08/2020				
Date of Comple:-	16/08/2021				
(1) Res-oolation of Rain cuts ————					

	$1 \times 30.0 \times 1.150 \times 0.30 = 10.35 \text{ m}^3$
	$1 \times 20.0 \times 1.250 \times 0.30 = 7.5 \text{ m}^3$
	$1 \times 30.0 \times 1.175 \times 0.30 = 10.575 \text{ m}^3$
	$7 \times 20.0 \times 1.150 \times 0.30 = 48.3 \text{ m}^3$
	$1 \times 30.0 \times 1.00 \times 0.30 = 9.00 \text{ m}^3$
	$\Sigma = 85.725 \text{ m}^3$

② Making up - Beom
Shoulder

1x	30.0x	1.250	=	37.5 m ²
2x	30.0x	1.150	=	69.0 m ²
4x	20.0x	1.150	=	92.0 m ²
3x	30.0x	1.250	=	112.5 m ²
4x	20.0x	1.000	=	80.0 m ²
			Σ =	391.00 m ²

Continuation

Abstract of Cost.

25

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Rain cuts—					
Qty, videp—(22)					
= 85.72 m ³ @ 379.59/m ³ = 32538.00					
② Making up Berms Shoulders—					
Qty, videp—(22)					
= 391.00 m ² @ 56.81/m ² = 22213.00					
③ Repair of pot holes with 75mm HBM—					
Qty, videp—(23)					
= 70.25 m ² @ 395.42/m ² = 27778.00					
④ Maintenance of BT Surface					
Qty, videp—(23)					
= 70.25 m ² @ 269.44/m ² = 18928.00					
⑤ Maintenance of CP H/P/C—					
Qty, videp—(23)					
= 3.00 NO @ 1102.80/NO = 3308.00					
⑥ Maintenance of CP Slab Culvert—					
Qty, videp—(23)					
= 1.00 NO @ 2273.47/NO = 2273.00					
⑦ Maint of Road Signs.					
Qty, videp—(23)					
= 0.18 km @ 1054.28/km = 193.00					

Continuation

Continuation

8/6/5/2024
J-R