

Schedule XLV-FORM No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/Work - main of Road from					
main Road Bardali pul to					
North Thidali via Bantariya.					
N/Agency - Singt Cons. Pvt. Ltd.					
Agg No - 15/ S.B.D/ 2019-20					
A.D.O.C :- 02-12-2020					
Date of measurement					
(1/1) Restoration of rain					
cuts - do - do - e/t					
11x 8.00x 0.70x 0.30 =					18.48m ³
12x 7.00x 0.80x 0.30 =					22.68m ³
10x 9.00x 0.70x 0.30 =					18.90m ³
11x 11.00x 0.90x 0.30 =					32.67m ³
12x 9.00x 0.70x 0.30 =					22.68m ³
11x 8.00x 0.90x 0.30 =					23.76m ³
12x 7.00x 0.80x 0.30 =					20.16m ³
11x 9.00x 0.90x 0.30 =					26.73m ³
Qty =					186.06m ³
(1/2) making up berms/					
shoulder - do - do - e/t					
12x 11.00x 0.90 =					118.80m ²
18x 14.00x 0.80 =					201.60m ²
15x 13.00x 0.80 =					156.00m ²
16x 11.00x 0.90 =					158.40m ²
14x 12.00x 0.80 =					134.40m ²
15x 14.00x 0.60 =					126.00m ²
13x 12.00x 0.50 =					78.00m ²
10x 14.00x 0.40 =					56.00m ²
Qty =					1029.20m ²
(3/3) Repair of pot holes					
filled with 75mm					
do - do - e/t					

Continuation

62

