

Particulars	Details of actual measurement				Content of area
	No.	L.	B.	D.	
Name of Road - Maintenance of Road					
From Chero - Nagarhauza PWD Road					
To Hindon Bigha ke Nagdik se gram					
Chidi Jagadpur.					
Agency - Sri Sanjay Kumar					
App. No - 92/SBD/2018-19					
Actual date of Completion - 29/01/2020					

RECORD ENTRY

① Restoration of rain cuts

.....					
	68	0.90	1.20	0.30	22.0320
	56	1.25	1.20	0.30	25.2000
	48	1.90	1.20	0.30	32.8320
	36	2.40	1.20	0.30	31.1040
	24	2.75	1.10	0.30	21.7800
					132.9480

② Maintenance of Earthen shoulder

.....					
	2	6	12.60	1.20	181.440
	2	8	18.40	1.20	353.280
	2	3	28.60	1.20	205.920
					740.640

③ Repair of Pot holes filled with BM

.....					
	62	0.60	0.60	0.075	1.6740
	48	0.90	0.75	0.075	2.4300
	36	1.25	0.90	0.075	3.0380

Continuation

7.1424

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	B.F.				Rs 289,777.2 2,64,453.2
③ Maintenance of H.P. Culvert (-)					
-----do-----do-----do-----do					Rs 1
4.00 Nos. VTM BP-64					
@ Rs 1107.77/Nos					Rs 4431.2
④ cutting of branches of trees					
-----do-----do-----do-----do					Rs 1
3.00 Nos. VTM BP-64					
@ Rs 105.65/Nos.					Rs 317.2
⑤ White washing of parapet walls					
-----do-----do-----do-----do					Rs 1
82.56 m ² VTM BP-64 & 65					
@ Rs 16.23/m ²					Rs 1340.2
					Rs 270541.2
less 0.25% Below					Rs 676.2
					Rs 2,69,865.2
For 25/03/25					
DE					
26/03/25					
(DE)					
DAD					
26/03/25					
DE					
Material Statement					
① e/w	244.04 m ³				
② S/clips	21.810 m ³				
③ Bitumen	1.294 m ³				
④ Emulsion	0.235 m ³				
⑤ Sand	0.980 m ³				

Continuation

For 25/03/25
DE