

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल दरभंगा-1
email-eerwddarbhangal@gmail.com

पत्रांक :- 1056 ११९९/
प्रेषक,

लहेरियासराय दिनांक 26.05-2025

ई0 कुमार चन्द्रज
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, दरभंगा-1

सेवा में,

अपर-मुख्य-कार्यपालक-पदाधिकारी,
ग्रामीण कार्य विभाग,
ब्राडा, पटना।

विषय:- MR New maintenance Policy 2018 योजना से संबंधित कार्यों के भुगतान हेतु
आवंटन उपलब्ध कराने के संबंध में।


महाशय,

उपर्युक्त बिषयक संबंध में कहना है, कि ग्रामीण कार्य विभाग, कार्य प्रमण्डल
दरभंगा-1 में MR New maintenance Policy 2018 योजना के अंतर्गत चल रहे कार्यों के
भुगतान हेतु विहित प्रपत्र में अधियाचना पत्र तैयार कर समर्पित किया जाता है।

अतः अनुरोध है, कि आवंटन शीघ्र उपलब्ध कराने की कृपा की जाय,
ताकि संवेदक को भुगतान किया जा सके।

अनु0:- यथोक्त विहित प्रपत्र में।

विश्वासभाजन


26/05/2025

कार्यपालक अभियंता,

ग्रामीण कार्य विभाग, कार्य प्रमण्डल, दरभंगा-1

Chel
26.5.25

26/5/25

FORM GFR 19-A

(See Government of India's Decision (1) below Rule- 150)

Form of Utilization Certificate up to the 13.05.2025

MR 3054 New maintenance Policy 2018

PIU- RWD, Works Division, Darbhanga-1

Sl. No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Rs. Lakh)	Particulars
1	MR 3054 New maintenance Policy 2018	BRRDA, Patna. Lt No-33 dt.- 10.05.2025	10714.88552	Certified that out of Rs. 10714.88552 Lakh (CFMS) received 10.05.2025 In favour of Executive Engineer, RWD work division Darbhanga-1. A sum of Rs 10573.62292 Lakh (CFMS) has been utilized for the purpose of MR 3054 New maintenance Policy 2018 as given in the margin for which it was sanctioned and that the balance of Rs 141.26260 Lakh (CFMS) remaining unutilized at the end of the period under.
	Total		10714.88552	


Certified that I have satisfied myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer
- All other codal formalities have been observed.

Physical Progress achieved :-

- Construction of Road Works.
- Construction of CD Works.


D. A. O.
R.W.D. Works Division
Darbhanga-1


26/05/2025
Executive engineer,
R.W.D. Works Division
Darbhanga-1

Name of Customer : M/S Jadbansh Kumar Singh
 Name of Work/ Road : Habidih Middle House of Bacha
 Lab Job number :
 Date : 26-05-2025
 Section No. : 360

Print Generate Report and Graph

Test Date : 26-05-2025 Road Name : Habidih Middle House of Bacha
 Machine No : 364 Road Type : (A) ASPHALTIC
 Start S No : Side : Interval
 Start E No :
 Weather :
 Start Location : Habidih Middl UIV Range : 2112 To 5000 mm/km
 End Location : Habidih Middl Dist Range : 0 To 1.2 0.1
 Equation : test

Redraw Graph Map View

File : D:\Bump Machine Darbh\2025\MS JADUVANSH\27.05.2025\1.1\RI - Copy.xls. Section No. : 360, Eqn : test
 Name of Customer : M/S Jadbansh Kumar Singh, Name of Work/ Road : Habidih Middle House of Bacha Thakur to

4112

UIV
mm/
km

3112

2112

Distance * 1000 m

0 0.1 0.2 0.3 0.4 0.5 0.6 0.7 0.8 0.9 1 1.1

Signature
 26/05/2025
 EE

Signature
 26/5/25

Name of Road- Habidih Middle House of Bacha Thakur to Habidih Middle.

Name of Agency- M/S Jadubansh Kumar Singh

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY	Latitude	Longitude	Event
26/5/25	11:53:36	360	0.1	330	20.3	3300	3566	ROAD	26.00198	86.11378	
26/5/25	11:54:13	360	0.1	320	15.1	3200	3414	G	26.00198	86.11378	Normal
26/5/25	11:54:43	360	0.1	280	19.2	2800	3319	G	26.00198	86.11378	Normal
26/5/25	11:55:08	360	0.1	310	10.1	3100	3426	G	26.00198	86.11378	Normal
26/5/25	11:55:24	360	0.1	270	20.2	2700	3112	G	26.00195	86.11379	Normal
26/5/25	11:55:45	360	0.1	280	18.3	2800	3313	G	26.00195	86.11379	Normal
26/5/25	11:56:00	360	0.1	290	17.5	2900	3155	G	26.00195	86.11379	Normal
26/5/25	11:56:34	360	0.1	300	15.1	3000	3540	G	26.00243	86.11361	Normal
26/5/25	11:57:09	360	0.1	320	18.7	3200	3685	G	26.00243	86.11361	Normal
26/5/25	11:57:31	360	0.1	290	12.1	2900	3426	G	26.00243	86.11361	Normal
26/5/25	11:57:56	360	0.1	270	20.2	2700	3199	G	26.00159	86.11384	Normal
IRI Average-							3378				

$$Y = 0 * X^2 + 1.136 * X + 132.5$$

$$X = 3112$$

$$Y = 3566$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

26/5/25

26/05/2025
AT

26/05/2025
ER