

Name of Belene: P.M. Singh and Bhairon Singh Shankar Thakur

**Schedule XLV-Form No. 134**

He is to Harizan Tola (M.H. Sy - 1003)

Length - 1.817 KM Agreement value = Rs 132.89986 kots

A.D.C. - 4.11.2020 Total Agreement value = Rs 1,48,59,162 = 10

21210 21210, 21210 DIVISION

21210 21210, 21210 SUB-DIVISION

Actual Date of Completion - 4.11.2020 2020-

**MEASUREMENT BOOK**

Sri Ramesh Kumar.

4th year maintenance

92

Sch. XLV—Form No. 134

| Particulars                 | Details of actual measurement |    |    |    | Contents of area |
|-----------------------------|-------------------------------|----|----|----|------------------|
|                             | No.                           | L. | B. | D. |                  |
| Name of Work -              | Maintenance of Road           |    |    |    |                  |
|                             | from Pankaj Pathy Bhawanipuri |    |    |    |                  |
|                             | Shankar Thakur Cher to        |    |    |    |                  |
|                             | Harjan 05/9                   |    |    |    |                  |
| Agency -                    | Shri Ramesh Kumar             |    |    |    |                  |
| Agreement No -              | 13/MKD/2019-20                |    |    |    |                  |
| Date of start -             | 09.08.2019                    |    |    |    |                  |
| Date of completion -        | 08.08.2020                    |    |    |    |                  |
| Actual Date of completion - | 04.11.2020                    |    |    |    |                  |
|                             | Record Measurement            |    |    |    |                  |
| (1)                         | Restoration of Rainfall       |    |    |    |                  |
|                             | with Soil moorm               |    |    |    |                  |
|                             | —                             |    |    |    |                  |

|    |     |       |      |                        |
|----|-----|-------|------|------------------------|
| 5x | 15x | 0.7x  | 0.32 | 15.75 m <sup>2</sup>   |
| 5x | 30x | 0.8x  | 0.32 | 36 m <sup>2</sup>      |
| 6x | 30x | 0.8x  | 0.32 | 43.2 m <sup>2</sup>    |
| 5x | 15x | 0.65x | 0.32 | 14.625 m <sup>2</sup>  |
| 6x | 15x | 0.6x  | 0.32 | 16.2 m <sup>2</sup>    |
| 6x | 15x | 0.5x  | 0.32 | 13.5 m <sup>2</sup>    |
| 5x | 8x  | 0.7x  | 0.32 | 8.4 m <sup>2</sup>     |
|    |     |       |      | 147.675 m <sup>2</sup> |
|    |     |       |      | 147.12 m <sup>2</sup>  |

|     |                        |  |  |  |  |
|-----|------------------------|--|--|--|--|
| (2) | Machting up of Dorry   |  |  |  |  |
|     | shoulder, stripping    |  |  |  |  |
|     | excise 9m <sup>2</sup> |  |  |  |  |
|     | —                      |  |  |  |  |

Continuation

# Abstract of work

96

Sch. XLV—Form No. 134

| Particulars                                            | Details of actual measurement |    |    |    | Contents of area |
|--------------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                        | No.                           | L. | B. | D. |                  |
| (1) Restoration of Rainwater<br>Gutter with galv. iron |                               |    |    |    |                  |
| — do — do —                                            |                               |    |    |    |                  |
| VP (92) idm (1) = 147.98 m <sup>2</sup>                |                               |    |    |    |                  |
| @ 380258/m <sup>2</sup> A                              |                               |    |    |    | 56010200         |
| (2) Making up of<br>Gutter channel                     |                               |    |    |    |                  |
| — do — do —                                            |                               |    |    |    |                  |
| VP (93) idm (2) = 868.30 m <sup>2</sup>                |                               |    |    |    |                  |
| @ 58237/m <sup>2</sup> A                               |                               |    |    |    | 50683200         |
| (3) Repair of pot<br>holes filled                      |                               |    |    |    |                  |

|                                          |  |  |  |  |          |
|------------------------------------------|--|--|--|--|----------|
| — do — do —                              |  |  |  |  |          |
| VP (95) idm (3) = 9.836 m <sup>2</sup>   |  |  |  |  |          |
| @ 11354262/m <sup>2</sup>                |  |  |  |  |          |
| — do — do —                              |  |  |  |  | 111684   |
| (4) Patch repair over<br>pot holes       |  |  |  |  |          |
| — do — do —                              |  |  |  |  |          |
| VP (94) idm (4) = 131.150 m <sup>2</sup> |  |  |  |  |          |
| @ 29324/m <sup>2</sup>                   |  |  |  |  |          |
| — do — do —                              |  |  |  |  | 38462200 |
| (5) Making up of<br>idm (Hume Pipe)      |  |  |  |  |          |
| VP (94) idm (5) = 3 Nos                  |  |  |  |  |          |
| @ 111700 (see 4)                         |  |  |  |  | 3351200  |

Continuation

| Particulars | Details of actual measurement |             |    |    | Contents of area |
|-------------|-------------------------------|-------------|----|----|------------------|
|             | No.                           | L.          | B. | D. |                  |
| (6)         | Measure of CP                 |             |    |    |                  |
|             | Work (stone corner)           |             |    |    |                  |
|             | — do —                        |             |    |    |                  |
| wp (85)     | Rate (6) = 1 Rs               |             |    |    |                  |
|             | @                             | 2309.04 / m |    |    |                  |
|             |                               |             |    |    | 2309.04          |
| (7)         | Measure of Road               |             |    |    |                  |
|             | Work — do —                   |             |    |    |                  |
| wp (95)     | Rate (7) = 0.27 Rs            |             |    |    |                  |
|             | @                             | 174.51 / m  |    |    |                  |
|             |                               |             |    |    | 290.20           |

|         |                     |             |  |  |         |
|---------|---------------------|-------------|--|--|---------|
| (8)     | Measure of 200M     |             |  |  |         |
| (9)     | and km stone        |             |  |  |         |
| wp (97) | Rate (9) = 0.33 Rs  |             |  |  |         |
|         | @                   | 652.52 / km |  |  | 214.20  |
| (9)     | Width work of       |             |  |  |         |
| "       | Parapet wall of     |             |  |  |         |
|         | half and top        |             |  |  |         |
|         | — do —              |             |  |  |         |
| wp (95) | Rate (9) = 61.92 Rs |             |  |  |         |
|         | @                   | 162.65 / m  |  |  | 1039.00 |
|         |                     |             |  |  | 264.037 |
|         | 140 225 / 2000      |             |  |  | 5941.20 |
|         |                     |             |  |  | 258096  |

Dr. K. M.  
03.07.25  
JC

Continuation

Shri. K. M.  
08/04/25  
AE