

MMGSY- 4039 to Jaduchar

Schedule XLV-Form No. 134

Ag.No- 31 SBD /2019- 2020

Sherghati

DIVISION

Moharpur

SUB-DIVISION

Name of Agency - Satyendra Kumar Yadavdai

Measurement Book

1255

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4 th year Mangarao Hall					
Name of work:- Construction of					
Road from 1029 TO					
Induchak under					
MH 154					
Name of contractor - Satyendra					
Kumar Pachwadu					
GT Will - Barma					
P.O. Govardha Malla					
P.S. Kanchi Ganga					
Agreement No - 21500/2020-21					
Date of work start - 23/06/2020					
Date of completion - 25/06/2021					
Measurement					
(1) Restoration of Barmaile/					
Barma					
16x 3.00x 0.80x 0.30 = 11.52m ³					
19x 2.00x 0.90x 0.30 = 10.26m ³					
15x 2.50x 0.70x 0.30 = 8.44m ³					
20x 3.00x 0.60x 0.30 = 12.96m ³					
					43.18m ³
					37.42m ³
(2) Making up of barma/					
Shoulder - striping					
25x 1.00x 0.90 = 19.80m ³					
25x 2.00x 1.00 = 50.00m ³					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	120	8.125	0.375		31.20 m ²
	260	7.125	0.350		88.40 m ²
					209.50 m ²
(3) Repair of pot holes filled with 75mm					
	420	0.65000	0.60000	0.075	0.11 m ²
(4) Patch repair over pot holes with 38mm concrete					
	420	0.65000	0.60000		1.56 m ²
	2800	0.80000	0.60000		13.44 m ²
(5) Patch repair over bituminous surface					
	240	0.75000	0.70000		19.50 m ²
	1100	1.50000	1.40000		16.50 m ²
	200	0.60000	0.60000		7.20 m ²
					37.20 m ²
(6) Filling of cracks					
quad 10m ² excluding					
	580	4.12			23.89 m ²
	300	2.50			7.50 m ²
	260	3.00			7.80 m ²
	380	2.40			9.12 m ²
					48.31 m ²

Continuation

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of Retaining Beams with soil.					
Page No. (87) Item No. (1)					
= 37.42 m ² R 386.14 m ³ R					4449 =
(2) Making up of forming/ Shoulder stripping excess soil from the Shoulder					
Page No. (88) Item No. (2)					
= 209.50 m ² R 57.36 m ³ R					2017 =
Fill - 12 to 15 cm					
Page No. (88) Item No. (3)					
= 0.11 m ² R 878.57 m ³ R					1087 =
4/4 Patch & borrow At road surface					
Page No. (88)					
= 37.20 m ² R 25.11 m ³ R					9392 =
5/5 Patch & borrow At road surface					
Page No. (88)					
= 37.20 m ² R 68.24 m ³ R					9979 =

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(6/6) Filling of cracks and joints on bridge Pg. No. (85) = 4.762 m @ Rs 3.96/m Rs 1886=					
(7/8) Repair of isolated area of damaged concrete pavement Pg. No. (86) = 22.97 m ² @ Rs 25.11/m ² Rs 5768=					
(8/9) Deposition and regrading Pg. No. (86) = 367.50 m @ Rs 23.46/m Rs 7220=					
(9/11) Maintenance of work (Hume pipe work) = 3.44 m @ Rs 1130.00 each Rs 33922					
10/14) Maintenance of Road @ Rs Pg. No. (86) = 0.814 km @ Rs 107.81/km Rs 877=					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(11/15) Maintenance of Dunny					
of 101 brick stone					
Page No. (96) = 0.94107					
@ Rs 68.22/101					Rs 517 =
(12/16) Cutting of branches					
of trees & shrubs					
Page No. (97) = 6.44100					
@ Rs 105.74 each					Rs 658 =
(13/18) Cutting of branches					
from Roadway					
Page No. (87)					
= 476 No					
@ Rs 6.73 each					Rs 3203 =
(14/19) Cutting of branches					
from Roadway					
Page No. (92)					
= 1074.00					
@ Rs 2.24/1074					Rs 2406 =
(15/20) White washing of					
from per					
Page No. (93) = 18.45100					
@ Rs 16.31/18					Rs 314 =
					Rs 73145 =
Add 12/1. GST 2 (4%)					Rs 7509 =
Labour cost					
Add Sep wire P.C.U.					Rs 107 =
					Rs 82761 =

Signature

11/02/23

Continued

11/02/23