

~~DR~~ Sahyadra Pragy Path to Cudaxiga tola

Schedule XLV-Form No. 134

Mammy (S.C)

Mam Mohan Keshin

DIVISION

DI 971E1

SUB-DIVISION

MEASUREMENT BOOK

3576

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>1st Year Maintenance work</u>					
Nilu. - Const ⁿ of Road from Sahiyana PMGSY					
Path to Gulariya Tola.					
Agst. No. -	113-	S.B.D	/020	-21	
Agency! -	Sri Mohan Mohan Krishna.				
Maintenance Period! -					
<u>Record Entry</u>					
① Restoration of Rain cut.					
	4x3.80	x0.90	x0.30	=4.10	m ³
	6x2.60	x0.80	x0.30	=3.74	m ³
	6x3.40	x0.90	x0.30	=5.51	m ³
	8x5.40	x0.90	x0.30	=11.66	m ³
	6x3.70	x0.80	x0.30	=5.33	m ³
					=30.34 m ³
② Maintenance of earthen shoulder.					
	6x4.90	x1.0	=29.40	m ²	
	4x3.40	x0.90	=12.24	m ²	
	8x6.30	x0.90	=45.36	m ²	
	5x5.10	x1.0	=25.50	m ²	
					=112.50 m ²
③ Maintenance of B.T. Surface Road.					
	6x1.55	x1.0	=9.30	m ²	
④ Maintenance of H.P. Culvert.					
					=3.0 No.
⑤ Cutting of branches of trees & shrub.					
=1.0 No.					

Continuation

Continuation

> 10 No.

~~C 48~~
~~Ann~~
19/08/24

Material Statement:-

9) Earth:-	39.63 m ³	@ 23.78/m ³	2L	942.0
				118.0