

प्रेसी रॉथ कान्दपुरा ते नाशिका जयरा जयरा

Schedule XLV-Form No. 134

7645809925 UEN

Dhobi tola

मनोर भय

DIVISION

Measurement

2

abstract

SUB-DIVISION

3107

MEASUREMENT BOOK

9701131

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	3rd	Year	Maintenance		Bill
Mtl:- PMGSY Path Chowdhuari Narkajyaha					
- Jagdax Dhobi Tolga					
Agt. Ntl:- 07-S.B.D./021-22					
Agency:- Manoj Rai					
Maintenance Period:- 9.5.24 to 8.5.25					
	Measurement				
① Restoration of Rain cuts					
22x6.70x0.90x0.30=39.80 M ³					
26x6.50x0.80x0.30=40.56 "					
14x4.10x0.70x0.30=12.05 "					
16x4.85x0.90x0.30=20.95 "					
					= 113.36 M ³
② Making up Barrowal Shoulder					
22x6.70x1.0=147.40 m ²					
28x7.10x0.80=159.04 "					
26x5.20x0.90=121.68 "					
24x5.70x0.90=123.12 "					
					= 551.24 M ²
③ Repair to pot holes by 75mm WBM					
16x3.20x1.10=56.32 M ²					
14x2.0x1.50=42.0 "					
					= 98.32 M ²
④ Patch Repair over pot holes					
14x2.40x1.30=43.68 M ²					
18x3.0x1.00=54.0 "					
					= 97.68 M ²

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B/P = 4	00594.0
⑪ Maintenance of planted tree					
Wide TM B/P = 70			140.0	ND	
@ Rs 588.0 each					82320.0
				= Rs 48	2914.0
1% L.C				= Rs	4829.0
12% GST				= Rs	57950.0
10% S.F.				= Rs	772.0
					Rs 546465.0
Less 8.75% Below				= Rs 4	7816.0
					Rs 498649.0
<u>Sumar</u>		<u>Vine</u>		<u>C.R.P</u>	
8/5/25		68/05/25		20/2/25	
		A.G.			