

# 3<sup>rd</sup> year maintenance

Sch. XLV-Form No. 134

| Particulars                 | Details of actual measurement |    |    |    | Contents of area         |
|-----------------------------|-------------------------------|----|----|----|--------------------------|
|                             | No.                           | L. | B. | D. |                          |
| Name of road -              |                               |    |    |    | Parga moaye to           |
|                             |                               |    |    |    | Parga moaye Hanzari talu |
| Agency -                    |                               |    |    |    | Sri Abhishek Kumar       |
| Agreement no -              |                               |    |    |    | 173-SRD/MR/24/2021-22    |
| Date of start -             |                               |    |    |    | 28.12.2021               |
| Actual date of completion - |                               |    |    |    | 06.05.2022               |

① Restoration of rain cuts.  
— do —

|         |      |      |      |   |                      |
|---------|------|------|------|---|----------------------|
| 2 x     | 4.50 | 1.40 | 0.25 | = | 3.15                 |
| 3 x     | 3.90 | 1.80 | 0.25 | = | 5.265                |
| 2 x     | 5.10 | 1.95 | 0.3  | = | 5.967                |
| 8 x     | 3.15 | 0.75 | 0.3  | = | 5.67                 |
| 9 x     | 2.90 | 0.80 | 0.3  | = | 6.26                 |
| 4 x     | 4.60 | 1.1  | 0.3  | = | 6.07                 |
| 6 x     | 3.80 | 0.90 | 0.3  | = | 6.15                 |
| Total = |      |      |      |   | 38.53 m <sup>3</sup> |

② Making up of Berm/shoulder  
— do — do —

|         |      |      |   |       |
|---------|------|------|---|-------|
| 1 x 6 x | 3.90 | 2.25 | = | 52.65 |
| 1 x 5 x | 3.9  | 1.70 | = | 33.15 |
| 2 x 5 x | 5.8  | 0.90 | = | 52.20 |
| 2 x 7 x | 2.8  | 0.71 | = | 27.83 |
| 2 x 3 x | 3.2  | 0.45 | = | 8.64  |

Continuation

| Particulars                     | Details of actual measurement |    |    |          | Contents of area |
|---------------------------------|-------------------------------|----|----|----------|------------------|
|                                 | No.                           | L. | B. | D.       |                  |
| <u>Material used</u>            |                               |    |    |          |                  |
| Earth work -                    |                               |    |    | 38.53    | m <sup>3</sup>   |
| Bitumean - S-70 -               |                               |    |    | 21.53    | Kg               |
| Emulsion - RS-1 -               |                               |    |    | 12.78    | kg               |
| stone chips -                   |                               |    |    | 52.7     | m <sup>3</sup>   |
| crushed sand -                  |                               |    |    | 10.5     | m <sup>3</sup>   |
| <u>Abstract</u>                 |                               |    |    |          |                  |
| 05/05/25                        |                               |    |    |          |                  |
| DE                              |                               |    |    |          |                  |
| <u>Abstract of cost</u>         |                               |    |    |          |                  |
| 1) Restoration of Rain cut - do |                               |    |    |          |                  |
| - do -                          |                               |    |    |          |                  |
| 38.53 cum vide Pg - (39)        |                               |    |    |          |                  |
| @ 404.06/cum — Rs               |                               |    |    | 15568=00 |                  |
| 2) Re Making up of berms        |                               |    |    |          |                  |
| - do -                          |                               |    |    |          |                  |
| 310.89 sqm vide Pg - (40)       |                               |    |    |          |                  |
| @ 60.48/sqm — Rs                |                               |    |    | 18803=00 |                  |
| 3/3 Repair of pot holes -       |                               |    |    |          |                  |
| - do - do                       |                               |    |    |          |                  |
| 42.6 sqm vide Pg - (40)         |                               |    |    |          |                  |
| @ 38.67 Limited                 |                               |    |    |          |                  |

Continuation

Continuation